
OPERATION MANUAL
ИНСТРУКЦИЯ ПОЛЬЗОВАТЕЛЯ

P.I.T.

PHM120-C





ELECTRIC MIXER


МИКСЕР СТРОИТЕЛЬНЫЙ


1050W Powerful Efficient


Please read the instruction manual carefully before use!
Пожалуйста, внимательно прочтите инструкцию перед использованием!



2
1
3


1
1
2


2
A
3
B


3


4
4


5

English

Safety Notes

General Power Tool Safety Warnings

WARNING Read all safety warnings and all instructions.

Failure to follow the warnings and instructions PD\ UHVXOW LQ HOHFWULF VKRFN¿UH DQG RU VHULous injury.

Save all warnings and instructions for fu - ture reference.

The term “power tool” in the warnings refers to your mainsoperated (corded) power tool or battery-operated (cordless) power tool.

Work area safety

- Keep work area clean and well lit. Cluttered or dark areas invile accidents.
- Do not operate power tools in explosive atmospheres. such as in the presence of flammable liquids, gases or dust. Power tools create sparks which may ignile the dust or fumes.
- Keep children and bystanders a way while operating a power tool. Distractions can cause you to lose control.

Electrical safety

- Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools. Unmodified plugs and matching outlets will reduce risk of electric shock.
- Avoid body contact with earthed or grounded surfaces, such as pipes, radi - ators, ranges and refrigerators. There is an increased risk of electric shock if your body is earthed or grounded.
- Do not expose power tools to rain or wet conditions. Water entering a power tool will increase the risk of electric shock.
- Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges and moving parts. Damaged or entangled cords increase the risk of electric shock.
- When operating a power tool outdoors, use an extension cord suitable for out - door use. Use of a cord suitable for outdoor use reduces the risk of electric shock.
- If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply. Use of an rcd reduces the risk of electric shock.NOTE The term “residual curert device (RCD)” may be redlaced by the term “ground faull circuit interrupter(GFCI)” or “earlh leakage circuit breaker (ELCB)”.

Personal safety

- Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influ - ence of drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.
- Use safety equipment. Always wear eye protection. Safety equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries
- Prevent unintentional starting. Ensure WKH VZLWFK LV LQ WKH R‡ S connecting to power source and/or battery pack, picking up or carrying the tool. &DUU\LQJ SRZHU WRROV Z on the switch or energising power tools that have the switch on invites accidents.
- Remove any adjusting key or wrench before turning the power tool on. A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- Do not overreach. Keep proper footing and balance at all times. This enables better control of the power tool in unexpected situations.
- Dress properly. Do not wear loose clothing or jewellery. Keep your hair, clothing and gloves away from moving parts. Loose clothes, jewellery or long hair can be caught in moving parts.
- If devices are provided for the connec - tion of dust ex- traction and collection facilities, ensure these are connected and properly used. Use of dust collection can reduce dust-related hazards.

Power tool use and care

- Do not force the power tool. Use the correct power tool for your application. The correct power tool will do the job better and safer at the rate for which it was designed.
- Do not use the power tool if the switch does not turn it on and off. Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- Disconnect the plug from the power source and/or the battery pack from the

power tool before making any adjust - ments ,changing accessories, or stor - ing power tools. Such preventive safety measures reduce the risk of starting the power tool accidentally .

- Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool. Power tools are dangerous in the hands of untrained users.
- Maintain power tools. Check for mis - alignment or binding of moving parts, breakage of parts and any other con - dition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- Keep cutting tools sharp and clean. Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be performed. Use of the power tool for oper- DWLRQV GL‡HUHQW IURP WKRVH LQWHQGHG FRXOG result in a hazardous situation.

Service

- Have your power tool serviced by a TXDOL¿HG UHSDLU SHUVRQ XVLQJ RQO\ LGHQ tical replacement parts. This will ensure that the safety of the power tool is maintained.

Electric Mixer safety warnings

1.Use the optional handle (if included with the tool kit). Loss of control of the instrument may result in injury.

2. If there is a risk of the cutting tool coming into contact with hidden electrical wiring or its own power cord when performing work, hold the power tool by the specially designed isolated surfaces. Contact with a live wire will also make metal parts of the tool live, resulting in an electric shock to the operator.

3. When performing work, always take stable position. When using the tool at a height, make sure there are no people below.

+ROG WKH WRRO ¿UPO\

5.Hands should be kept away from rotating parts.

6.Do not leave a running tool unattended. Switch on the tool only when it is in your hands.

7. Immediately after finishing work, do not touch the drill bit or workpiece. They can be very hot and cause skin burns.

8.Some materials may contain toxic chemicals. Accept appropriate precautions,to avoid inhalation or contact with the skin of such sub- VWDQFHV 2EVHUYH WKH UHTXL in the Material Safety Data Sheet.

Product description and ›pecifi - cations

Read all safety warnings and all in - structions. Failure to follow the warnings and instructions may result LQ HOHFWULF VKRFN ¿UH DQG

Intended •se

The electric manual mixer is designed for mixing components (dry mixture and liquid), for obtaining various building and finishing materials (concrete, plaster, tile and wallpaper adhesives, dispersed paints, etc.).

Technical data

Model	PHM120-C
3BUFE 7PMUBHF	9a +]
3BUFE 1PXFS	1050 W
Chuck maximum di- ameter	‘ PP KRVH LQWHQGHG FRXOG
/P MPBE TQFFE	U PLQ
.JYJOH EJBNFUFS	‘ PP
8FJHIU	5 kg XVLQJ RQO\ LGHQ

Contents of delivery

Electric Mixer	1pc
Mix Tool	1pc
M14 tool connection shaft	1pc
16mm Chuck	1pc
Wrench	2pcs
D-shaped handle	1pc
Instruction manual	1pc

Note

Since the product is constantly being improved, P.I.T. reserves the right to make changes to the specifications and product VSHFL¿FDWLRQV VSHFL¿HG KHU tice.

Product features

The numbering of the components shown refers to the representation of the power tool on the graphic pages.

1. Trigger switch
2.Lock button
3.Reversing switch lever
4.Chuck key

Assembly

Always make sure that the tool is turned off and that the power cord is unplugged before making any adjustments or checking the operation of the tool.

Switch action

Before plugging in the tool,always check that the trigger switch works properly and returns WR WKH 2)) SRVLWLRQ ZKHQ UHOHDVHG

To turn on the tool, simply press the trigger switch. To increase the number of revolutions, press the trigger switch harder. Release the trigger to stop the tool.

To operate the tool continuously, depress the trigger, then depress the lock button and release the trigger. To disengage the locked position of the switch, fully depress the switch trigger and then release it.

Reversing switch action

Always check the direction of rotation before operation.

Use the reversing switch only after the tool has come to a complete stop. Changing the direction of rotation before the tool comes to a complete stop may damage the tool.

If you cannot press the trigger switch, make sure the reversing switch is set exactly to the (A side) or (B side) position.

This tool has a reversing switch to change the direction of rotation. Move the reverse lever switch to position (side A) for clockwise rotation or position (side B) for counterclockwise rotation.

Mounting

Always make sure that the tool is turned off and that the power cord is unplugged before doing any work on the tool.

Installing the top handle

Firmly tighten the top handle on the tool.

Installing or removing a drill

To install the drill, insert it into the chuck as far as it will go. Tighten the chuck by hand. Insert the chuck key into each of the three holes and tighten it clockwise. Be sure to tighten all three chuck holes evenly.

To remove the bit, turn the chuck wrench counterclockwise in one hole only, then unscrew the chuck by hand.

After working with the chuck key, be sure to put the key back in place.

Exploitation

Drilling

Always use the top or rear handle (optional) DQG KROG WKH WRRO ¿UPO\ E\ dle and switch handle during operation.

Drilling in wood

When drilling in wood, best results are obtained with wood drill bits fitted with a lead screw. The lead screw makes drilling easier by holding the drill in the workpiece.

Metal drilling

To prevent the drill bit from slipping when starting drilling, make an indentation with a center punch and a hammer at the drilling point. Insert the tip of the drill into the recess and start drilling.

When drilling in metals, use cutting lubricant. The exception is cast iron and brass, which must be drilled dry.

Excessive pressure on the tool will not speed up drilling. In fact, excessive pressure will only damage your drill tip, reduce tool performance and shorten tool life.

When the hole being drilled becomes through, D VLJQLILFDQW IRUFH LV DSS +ROG WKH WRRO ¿UPO\ DQG E drill begins to pass through the workpiece.

A stuck drill bit can be removed by simply switching the reversing switch to reverse reverse rotation. However, the tool may reverse WRR TXLFNO\ LI QRW KHOG ¿UP

Always secure small workpieces in a vise or similar clamping device.

Avoid drilling into material that you think may have hidden nails or other things that could cause the drill to jam or break.

Maintenance and Service

Maintenance and Cleaning

y 3XOO WKH SOXJ RXW RI WKH carrying out any work on the power tool.

y 7R HQVXUH VDIH DQG H^FLHQ always keep the power tool and the venti - lation slots clean.

In order to avoid safety hazards, if the power supply cord needs to be replaced, this must be done by P.I.T. or by an after-sales service centre that is authorised to repair P.I.T. power tools

Storage and transportation

Store the instrument in closed rooms with natural ventilation in a package at an air temperature from 0 ° C to + 50 ° C and an air humidity of no more than 80%.

Products can be transported by any type of closed transport in the manufacturer's packaging or without it, while preserving the product from mechanical damage from atmospheric precipitation. Remove the battery and


accessories from the tool before transporting.

Dispose of waste

Damaged power tools, batteries, accessories and waste packaging materials must be recycled and reused in an environmentally friendly manner.

'R QRW WKURZ SRZHU WRROV DQG EDWWHULHV batteries into general household waste!

Product serial number interpreta - tion serial number



The date of manufacture of the product is encoded in the serial number printed on the ERG\ RI WKH WRRO 7KH ¿UVW GLJLWV LQGLFDWH WKH year of issue, the next 2 digits indicate the month.

TERMS OF WARRANTY SERVICE

To customers (users) of warranty service:

1. This warranty certificate is the only docu- PHQW WKDW FRQ¿UPV \RXU UJKW WR HDUQ ZDUUDQW\ service. If this proof is not presented, no FODLPV ZLOO EH DFFHSWHG DUUDQW\ FDUGV cannot be recovered if lost or damaged.

2. It is required to provide a valid and legal document for purchasing the product. The document must have the name or seal of the sales company; at the same time, state the full model name of the purchased P.I.T. product, the serial number on the nameplate of the fuselage, and the date of purchase, and the required warranty. The whole machine and its accessories.

The warranty period:

1. The warranty period of the product is 12 months from the date of sale. During the warranty period, the service department will eliminate manufacturing defects free of charge and replace the parts that fail due to the manufacturer's fault. In warranty repair, an equivalent operable product is not provided. Replaceable parts become the property of the service provider.

2. The wear degree on the diameter of the motor rotor commutator is less than 0.4 mm (except for brushless motor tools), and the internal damage caused by the quality of the tool belongs to the warranty.

The following situations occur during the warranty period, which is not covered by the warranty:

1. In the absence of any valid legal docu- PHQWV LQYRLFHV VXFK DV ZD and warranty cards to prove the date of purchase.

2. Damage caused by natural wear and overload. (For example, motor rotor and stator failure caused by overload, scorching or melting of the primary winding of the welding machine transformer, charging or starting the charging device, melting of internal parts, burning of electronic circuit boards, etc.)

3. The casing and power cord are mechanically damaged, as well as damage caused by corrosive media and high and low temperature, foreign objects entering the ventilation network of the motor, and damage caused by improper storage (corrosion of metal parts);

4. Damage caused by improper carrying, transportation and storage by users.

5. Products that are opened, repaired, re- SODFHG RU PRGL¿HG E\ XVHUV

6. Any damage caused by indiscriminate use, beyond the scope of use of the tool, and not in accordance with the instructions for use and maintenance. (see chapter "Safety Precautions" in the manual)

7. The damage caused by the following situations is not guaranteed due to improper use and non-quality problems:

(1) When the power tool is running at high speed, use the braking device to forcibly stop the rotation.

(2) Excessive pressure is applied to the tool during the use of the tool.

(3) Use the tool outside the scope of its purpose and capabilities.

(4) Damage caused by the tool working in a dusty environment for a long time without timely maintenance of the tool.

(5) Change the rotation direction of the work head before the tool stops completely.

(6) Shock the battery or charger and replace the plug of the charger without permission, causing damage to the battery or charger.

(7) Damage caused by two-stroke gasoline tools not being fueled in the correct proportions.

The warranty does not include:

1. Replacement of accessories (accessories and components) such as batteries, discs, blades, drills, drills, chucks, chains, sprockets, collet clamps, guide rails, tension and fastening elements, dresser heads, grinders And belt sander base machine, hexagonal head, etc.;

2. Wearing parts, such as: carbon brushes, transmission belts, seals, protective covers,

guide rollers, guide rails, rubber seals, bearings, toothed belts and wheels, shanks, brake belts, starter ratchets and ropes, piston rings Wait.

The above accessories are replaced with paid services during the warranty period;

Jmkkdbc

H[sb_ mdZaZgby ih l_ogbd_ [_ahiZkghklb ^ey we_dljhbgkljmf_glh\
IJ?>MIJ?@>?GB? Ijhqlbl_ \kmdZaZgby b bgkljmdpbb ih l_ogbd_ [_ahiZkghklb
G_kh[ex^_gb_ mdZaZgbc b bgkljmdpbb ih l_ogbd_ [_ahiZkghklb fh`_l-klZlv ljbdb ghc ihjZ`_gby we_dljbq_kdbf-lhdhf jZ b ly`_euo ljZ\f
KhojZgycl_ wlb bgkljmdpbb b mdZaZgby ^ey [m^ms_]h bkihevah\Zgby
Bkihevah\Zggh_ \ gZklhysbo bgkljmdpbyo b mdZaZgbyo ihgylb_ ©we_dljhbgkljmf_glh jZkijhkljZgy_lky gZ we_dljhbgkljmf_glh ibIZgb_f hl k_lb k k_l_\uf rgmjhf Zddmfmeylhjguc we_dljhbgkljmf_glh k_l_\h]h rgmjZ

;_ahiZkghklv jZ[hq_]h f_klZ

y Kh^_j`bl_ jZ[hq__ f_klh \ qbkljhl_ ohjhrh hk_s_ggu_ kihjy^hd beb g_hk_s_ggu_ mqZkldb jZ[hq_]h fh]ml ijb_klb d g_kqZkIguf kemqZ_f
y G_ jZ[hlZcl_ k wlbf we_dljhbgkljm f_glhf \h \aju\hhiZkghf ihf_s_gbb \ dhlhjhf gZoh^ylky wlh jxqb_ `b^dhklb \hkieZf_gyxsb_kv]Zau beb iueb beb iZjh\
y <h \j_fy jZ[hlu k we_dljhbgkljm f_glhf g_ ^himkdZcl_ [ebadh d <Zr_fm jZ[hq_fm f_klm ihklhjhggbo ehbe_drbkv <-u fh `_l_ ihl_jylv dhgljhev gZ^ we_dljhbgkljmf_glhf

We_dljh[_ahiZkghklv

y Rl_ik_evgZy \bedZ we_dljhbgkljm f_glZ ^he`gZ ih^oh^b rl_ik_evghc jha_ld_ Gb \gu_ kemqZ_ g_ baf_gycl_ rl_ik_evgm \bedm G_ ijbf_gycl_ i_j_oh^ rl_d_ju ^ey we_dljhbgkljmf_glh aZsblguf aZa_fe_ggb_f gu_ rl_ik_ev gu_ \bedb b ih^oh^ysb rl_ik_evgu_ jha_ldb kgb`Z-xl jZ`_gby we_dljhlhdhf
y lj_^hl\jZsZcl_l_e_kgucdhgIZdf aZa_fe_ggufb ih_joghklyfb lh k ljm[Zfb we_f_glZfb hlhie_gby dmohggufbieblZfb boheh^bevgbdZ fb ljb aZa_fe_gbb <Zr_]h l_eZ rZ_lky jbkd ihjZ`_gby we_dljhlhdhf
y AZsbsZcl_ we_dljhbgkljmf-gl hl `^y b kujhklbjhgbdgh\_gb_ \h^\ \ we_dljhbgkljmf_gl ih\urZ_l ihjZ`_gby we_dljhlhdhf
y G_ jZaj_rZ_lky bkihevah\Zlv r g_ ih gZagZq_gbx gZijbf_j ijZgkihjlbjh\db beb ih^_kdb we +jhbgkljmf_glZ beb ^ey \uly]b gby \bedb ba rl_ik_evghc jha AZsbsZcl_ rgmj hl \ha^_ck \ukhdbo l_fi_jZlmj fZkeZ hkl djhfhd beb ih^\b`guo qZkl-_c w ljhbgkljmf_glZ \j_`^_gguc beb kImfZgguc rgmj ih\urZ_l jb-kd ihj gby we_dljhlhdhf
y ljb jZ[hla_ k we_dljhbgkljmf_g h\ h-djuluf g_[hf ijbf_gycl jb\ ^gu_ ^ey wlh]h dZ[-_eb gbl_eb jbf_g_gb_ ijb]h^gh]h jZ[hlu-in^ hldjuluf g_[hf d-Z[_ey ebgbl_ey kgb`Z_l jbkd ihjZ`_gby ljhlhdhf
y -keb g_\hafh`gh ba[_`Zlv ijb g_gby we_dljhbgkljmf_glZ \ ku hnf_s_gbb ih^dexqZcl_ we_dljh kljmf_gl q_j_a mkljhckl\h aZsblg hldexq_gby kgb`Z aZsblgh]h hldexq_gby kgb`Z

ahiZkghklv ex^_c

y m^vl_ \gbfZl_evgu ke_^bl_ aZ qlh-^_eZ_l_ b ijh^mfZggh gZqb jZ[hlm k we_dljhbgkljmf_glhf jhevamcl_kv we_dljhbgkljmf_ \ mkjZehf khklhygbb be-b ih^ _ckl\b_f gZjdhlbdh\ Zedh]hey e_dZjkl_gguo kj_^kl\g fhf_gl g_\gbfZl_evghklb ijb jZ[-hl_ k ljhbgkljmf_glhf fh`_l ijb_klb d jv_aguf ljZ\fZf
y lj_^hl\jZsZcl_ g_ij_^gZf_j_ggh dexq_gb_ we_dljhbgkljmf idZd^ ih^dexq_gb_f we_dljh kljmf_glZ d we_dljhibIZgbx b b ZddmfmeylhjguclZ \udexq_ ghf khklhygbb we_dljhbgkljm ljZgkihjlbjh\d_ we_dljhbgkljmf_ ih^dexq_gb_ d k_lb ibIZgby \dex

]h we_dljhbgkljmf_glZ qj_\-Zlh gijbqZkmlkl\bb m gbo `bag_ggh]
gufb kemqZyfb
beb agZgbc _keb hgb g_ gZoh
y M[bjZcl_ mklZgh\hqguc bgkljmdhgljhe_f beb g_ ijhbgkljmdlbj
beb]Z_qgu_ dexqb ^h \dexq[_gbkyhevah\Zgbb we_dljhbgklj
we_dljhbgkljmf_glZ bgkljmf_gl bebebphf hl_lkl_gguf aZ-bo [_
dexq gZoh^ysbcky \h \jZsZxgsh_kdky
qZklb we_dljhbgkljmf_glZ- fhljbljhg_gb_ we_dljhbgk-ljmf_
_klb d ljZ\fZf
|Z bh[jZs_gb_ k gbf
y G_ ijbgbfZcl_ g__kl_kl\ggh
iheh`_gb_ dhjimkZ l_eZ -<k_]Z_qgu_ ^ey <Zr_c jZ
gbfZcl_ mklhcqb\h_ iheh`_gb_ Bkihevamcl_ ^ey <Zr_c jZ
kh ojZgycl_ jZ\gh_ekZh^Zjy \j_^gZagZq_gguc ^ey wlh]h we_
wlhfm <u fh`_l_ emqr_ dhgljhebjm\Zly bgkljmf_gl ih^oh^ysbcf_dljh
we_dljhbgkljmf_gl \ g_h`b^Zggu_ kb bgkljmf_glhf <u jZ[hlZ_l_ em
lmZpbyo gZ^_ g__ \ mdZaZgghf ^b-ZiZah
ghklb
y Ghkbl_ ih^oh^ysmx jZ[h-qmx y G_ jZ[hlZcl_ k we_dljhbgkljmf_g
`^m G_ ghkbl_ rbjhdmx h -ijb g_bkijZ\ghf \udexqZW-e_d
mdjZr_gby >_j`bl_ \hehku h^ xm
b jmdZ\bpu \^Zeb hl ^\b`m-sboky -jhbgkljmf_gl dhlhjuc g_ ih^
kl_dRbjhdZy h^_`^Z mdjZr_gby \dexq_gbx beb \udexq_gbx hi
^ebggu_ \hehku fh]ml [ulv aZlyg-mu \beb
\jZsZxsbfbky qZklyfb y >h^gZqZeZ gZeZ^db we_dljh
y ljb gZebqbb \hafh`ghklb mklZgh\db f_glZ i_j_^ aZf_ghc ijbgZ^e_`
iue_hlkZku\Zxsbo b iue_k[hjguo kl_c b ij_djZs_gb_f jZ[hlu-hlde
mkljhckl\ ijh_jycl_ bo ij-bkh_k dZcl_ rl_ik_evgmx \bedm hl jha
g_gb_ b ijZ\bevgh_ bkihevah\Zgby -lb b beb \ugvl_ Zddmwhe ylh
ljbf_g_gb_ iue_hlkhkZ fh`_l kgbabv g_lj_^gZf_j_ggh_ \dexq_gb_ we
hiZkghklv kha^Z\Z_fmx iuevx bgkljmf_glZ
y <GBF:GB? < kemqZ_ \hagbdgh\gby y Ojgbl_ we_dljhbgkljmf_gl-u \ g_
i_j_[hy \ jZ[hl_ we_dljhbg-kljmf_g kmighf ^ey ^_l_c f_kl_ -G_ jZ
lZ \ke_^kl\b_ ihegh]h beb qZklbq rZcl_ ihevah\Zlvky we_dljh- bgk
gh]h ij_djZs_gby wg_j]hkgZ[`_ -gby_ -gby hf ebpZf dhlhju_ g_ agZd
beb ih\j_`^_gby p_ib mijZ\e_ -k gbf beb g_ qblZeb gZk-lhysb
wg_j]hkgZ[`_gb_f mklZgh\bl -k gu -kljmdpbw we_dljhbgkljmf_glu hiZk
dexqZl_ev \ iheh`_gb_ <-ude mf_dZo g_hiulguo ebp
^b\rbkv qlh hg g_ aZ[ehdbh_g \ jmdZo g_hiulguo ebp
ijb _]h gZebqbb Hldex-qbl_ y Ls_Zl_evgh moZ`b\Zcl_ aZ we
\mx \bedm hl jha_ldb be-b hlkh -bgkljmf_glhf ljh_jyc-l_ [_
gbl_ ktzfguc Zddmfmwe ylhj ij_qgmx nmgdpbx b oh^ ^\b`msb
ij_^hl\jZsZ_lky g_dhgljhebjm fuc qZkl_c we_dljhbgkljmf_glZ
ih\lhjguc aZimkd k-\b_ ihehfhd beb ih\j_`^_g
y D\Zebnbpbjh\Zgguc i_jk-hgZe hljbpZl_evgh \ebyxsbo gZ nmgd
hl_lkl\bb k gZklhysbf jmdh\h^ we_dljhbgkljmf_glZ lh\j_`^_gg
ih^jZamf_\Z_l ebp dhlhju_ ag gZklhfu k j_]mebjh\dhc fhglZ`hf -\\h^hf wdk ^h bkihevah\Zgby we_dl
iemZlZpbx h[kem`b\Zgb_f we_dljhbg kljmf_glZehoh_ h[kem`b\Zgb_ we
kljmf_glZ -ljhbgkljmf_glh\ y\ey_lky ijb
[hevrh]h qbkeZ g_kqZklguo kem
y D jZ[hl_ k we_dljhbgkljmf_glhf ^hjml_ j_`msbc bgkljmf-gl \
kdZxlky ebpZ g_ fheh`_ -e_l pamgb_ hq gbf b qbklhf khklAZgbb
rb_ l_ogbq_kdh_ hibkZgb_ bgkljmdpbx eb\h^oh`_ggu_ j_`msb_ bgkljm
ih wdkiemZlZpbb b ijZ\be-Z [_ah\Zkgh k hkljufb j_`msbfb djhfdZfb
klb aZdebgb\Zxlky b bo e_]q_ _klb
y Ba^_eb_ g_ ij_^gZagZq_gh ^ey bkihev y ljbf_gycl_ we_dljhbgkljmf-gl ij
ah\Zgby ebpZfb \dexqZy ^_l_c k\hgb
`_ggufb nbabq_kdbfb qm\kl\ gZ^e_ ghklb jZ[hqb_ bgkljmf_
beb mfkl_ggufb kihkh[ghklyfb beb -gguf-b \ khhl_lkl\bb k gZklhys

bgkljmdpbyfb Mqblu\Zcl_ ijbMwmlsf gby \ hlghr_gbb mdZaZgbc k
jZ[hqb_ mkeh\by b \uiheg_gbb jZ[hl \k_]^Z aZgbfZcl_
jZ[hlmBkihevah\Zgb_ we_dljhbgkljmf_glZ gZ \ukhl_ m[_^bl_kv \ jhlkmh\
f_glh\ ^ey g_ij_^mkfhlj_gguo h jZ[hl ly`_euo ljZ\f
fh`_l ijb_klb d hiZkguf kblmZgbyf

K_j\bk

y J_fhgl <Zr_]h we_dljhbgkljmf_glZ
ihjmqZcl_ lhevdh d\Zebnbpbjh\Zgo
ghfm i_jkhgZem b lhevdh k ijbf
gb_f hjb]bgZevguo aZiZkguo qZkdZeh\ [_lhgZ rlmdZlmjdb iebl
Wlbf h[_ki_qb\Z_lky [_ahiZkghklb
we_dljhbgkljmf_glZ

MdZaZgby ih l_ogbd_ [_ahiZkghklb ^ey gZkl hevguo rebnh\Ze Yguo fZrbg

Bkihevamcl_ ^hihegbl_evgmx jmqdmTY_LkWbhYLk [Z
\oh^bl \dhfie_dl bgkljmf_glZ MljZMbWgkQXLk XZe <l
ljhey gZ^ bgkljmf_glhf fh`_l ijZ_^klb
dljZ\f_

?keb ijb \uiheg_gbb jZ[hl-kmsZkljmf
ljbkd dhglZdlZ j_`ms_]h bgkljmf_gZ
kdjulhc we_dljhijh\h^dhc b-eb
guf rgmjhf iblZgby ^_j`bl_-we_dljhbg
kljmf_gl aZ ki_pbZevgh ij_^gZagZq_ggu_
bahebjh\Zggu_ ih_joghklb
ijh\h^hf ih^ gZijy`_gb_f ijb\_^_l d ihjZ`_gbx hi_jZlhj-Z we_dljhbg
lhfm qlh f_lZeebq_kdb_ ^_lZeebq_kdb_
f_glZ lZd`_ [m^mlih^ gZijy`_gb_f
ijb_^_l d ihjZ`_gbx hi_jZlhj-Z we_dljhbg
q_kdbf lhdhf

ljb \uiheg_gbb jZ[hl \k_]^Z aZgbfZcl_
mklhcqb\h_ iheh`_gb_ ljb bkihevah\Zgbb
bgkljmf_glZ gZ \ukhl_ m[_^bl_kv \ jhlkmh\
kl\bb ex^_c \gbam

Dj_idh ^_j`bl_ bgkljmf_gl
Jmdb ^he`gu gZoh^blvky gZ jZkkhryguo
hl \jZsZxsboky ^_lZe_c

G_ hklZ\eycl_ jZ[hlZxsbc bgkljmf_gZ
[_a ijbkfhljZ <dexqZcl_ bgkljmf_gZ
lhevdh lh]^Z dh]^Z hg gZoh^blvky \ mdZb
KjZam ihke_ hdhgqZgby- jZe hby_ ijb
dZkZcl_kv d [bl_ k_jeZ beb ^bkihevah\Zgby
fh]ml [ulv hq_gv]hjyqbfb qlh ijb_^_l
h`h]Zf dh`b

G_dhlhju_ fZl_jbZeu fh]ml- kh^_j`Z
lhdkbqgu_ obfbq_kdb_ _s_kl\Z ijbfkl\
khhl_lkl\mxsb_ f_ju ij_^hklhjh`ghklb
qlh[u ba[_`Zlv \^uoZgby beb dhglZdlZk
dh`_c lZdbo _s_kl\ Kh[ex^Zcl_ ij_]h
\Zgby mdZaZggu_ \ iZkihjl_ [_ahiZkghklb
fZl_jbZeZ

HibkZgb_ ijh^mdlZ b mkeh

ljhqlbl_ \k_ mdZaZgby b bgkljmd
pbb ih l_ogbd_ [_ahiZkghklb

Fbdk_j Kljhbl_evguo

GZagZq_gb_

Fbdk_j jmqghc we_dljbq-kdb
afgZdlZg ^ey i_j_f_rb\Zgby dhfih
kmeh\c kf_kb b `b^dhklb ^ey i
jZaebqguo kljhbl_evguo b hl^_ehq
_Zkdlzeh\ [_lhgZ rlmdZlmjdb iebl
h[cguo de__\ ^bki_jkguo djZkhd

L_ogbq_kdb_ oZjZdl_jbklbd

Fh^ey	PHM120-C
9L[\kRQYTQ	<
CL]^Z^L N\LeQYTk	h[fbg
	Ø ff
	Ø ff
	d]

Dhfie_dl ihklZ\db

Fbdk_j bgkljmbl_evguc
ijh^ey i_j_f_rb\Zgby
ff iZljhg
Dexq
ih[jZagZy jmdhyldZ
Jmdh\h^kl\h ihevah\Zl_ey

Ijbf_qZgb_

Zd dZd bgkljmf_gl 3,7 ihklhyg
r_gkl\m_lky dhfiZgby hklZ\ey_l a
ijZ\h \ghkblv baf_g_gby \ md
a^lkvr l ogbq_kdb_ oZjZdl_jbklb
ie dlZbjx [_a ij_^\Zjbl_evg-h]h m

Blkhjl_gbggu_ khklZ\gu_ qZ

\uiheg_gZ ih bah[jZ`_gbx gZ kljZg
beexkl\Zpbyfb
Dmjdh\uc \udexqZl_ev
Dghidz [ehdbjh\db
Jufqz]j__jkb\gh]h i_j_dexqZl_ey
_Dexq aZ`bfgh]h iZljhgZ

K[hjdZ

\ jdb jZ[hlu bgkljmf_glZ \k_]^Z
ycl_ qlh bgkljmf_gl \udexq_g
ibl Zgby \ugml ba jha_ldb

>_ckl\b_ \udexqZl_ey
l_j_^ \dexq_gb_f bgkljmf_glZ \ jha_ldm_
\k_]^Z ijh_jycl_ qlh ljb]]-jgu^_
dexqZl_ev jZ[hlZ_l gZ^e_`Zsbf h[jZahZ
b \ha\jZsZ_lky \ iheh`_gb_ <UDE
_]h hlimklblv
>ey \dexq_gby bgkljmf_glZ ^h
ijhklh gZ`Zlv dmjdh\uc \udexqZl_ev
m_ebq_gby qbkeZ h[hjhlh\ gZ`fbl_
\uc \udexqZl_ev kbevg_c >ey
bgkljmf_glZ hlimklbl_ dmjdh\uc
l_ev
>ey g_ij_ju\ghc jZ[hlu bgkljmf_glZ
gZ`fbl_ gZ dmjdh\uc \udexqZl_ev
gZ`fbl_ dghidm [ehdbjh\db
dmjdh\uc \udexqZl_ev >ey
aZ[ehdbjh\Zggh]h iheh`_gby \udexqZl_ev
^h dhgpZ gZ`fbl_ gZ dmjdh\uc
l_ev Z aZl_f hlimklbl_ _]h
>_ckl\b_ j__jkb\gh]h i_j_dexqZl_ev
l_j_^ jZ[hlhc \k_]^Z ijh_jycl_
e_gb_ \jZs_gby
lhevamcl_kv j__jkb\guf i_j_dexqZl_ev
e_f lhevdh ihke_ iheghc hklZgh\db
f_glZ Baf_g_gb_ gZijZ\e_gby
^h iheghc hklZgh\db bgkljmf_glZ
ijb_klb d _]h ih\j_`^_gbx
?keb g_ m^Z_lky gZ`Zlv ljb]]-jgu^_
dexqZl_ev m[_^bl_kv qlh j__jkb\guf
i_j_dexqZl_ev mklZgh\e_g lh-qgh_the
gb_ klhjhgZ $ bekhjhgZ %
>Zgguc bgkljmf_gl bf__l j__jkb\guf
j_dexqZl_ev ^ey baf_g_gby gZijZ\e_gby
\jZs_gby l_j__^bl_ juqZ] j__jkb\gh]h
i_j_dexqZl_ey \ iheh`_gb_ klhjhgZ
: ^ey \jZs_gby ih qZkh\hc klj_edb
\ iheh`_gb_ klhjhgZ < ^ey \jZs_gby
ijhlb\ qZkh\hc klj_edb

FhglZ`

l_j_^ ijh_^_gb_f dZdbo eb[hjZ_l_
bgkljmf_glhf \k_]^Z ijh_jycl_
kljmf_gl \udexq_g Z rgmj iblZgby
ba jha_ldb
MklZgh\dZ _jog_c jmqdb
Dj_idh aZly]b\Zcl_ _jogxx jmdhyldm gZ
bgkljmf_gl_
MklZgh\dZ beb kgylb_ k_jeZ
>ey mklZgh\db k_jeZ \klZ\vl_
jZ \ aZ`bfghc iZljhg AZlygbl_
iZljhg jmdhc <klZ\vl_ dexq
iZljhgZ \ dZ`^h_ ba lj_o hl_jklbc
gbl_ _]h ih qZkh\hc klj_ed_
aZly]b\Zcl_ \k_ ljb hl_jklby
jZ\ghf_jgh
>ey kgylby [blu ih_jgbl_ ijb_klb

dexq ijhlb\ qZkh\hc klj_edb-lhevc
qhf hl_jklbb aZl_f jZkdjmlbl_
jmdhc
lhkZ_jZ[hlu k dexqhf aZ`bfgh]h iZ
bgyaZl_evgh deZ^bl_ dexq gZ f_kl
Wdkiem ZlZpby
K_je_gb_ \ ^_j__ gZ-bemq
ijb kihevamcl_ _jogxx jmqdm b jmqdm k \ude
K_je_gb_ f_lZeeZ
>ey ij_^hl\jZs_gby kdhev`_gby
gZijZ\ZqZe_ k_je_gby k^_e-Zcl_
gb_ k ihfhsvx d_jg_jZ b fhehldZ
dhdmgkljZqgbl_ k_jeblv
\jZs_gby je_gbb f_lZeeh\ bkihe
klZ\adm ^ey j_adb Bkdexq_gb_ k
qm]mg b eZlmgv dhlhju_ gZ-^h k\
kmoh
Qj_af_jgh_ gZ`Zlb_ gZ bgkljm
mkdhjbl-k_je_gb_ GZ kZfhf ^_e
f_jgh_ ^Z\e_gb_ lhevdh ih-\j_^b
gZijZ\e_gby
jevghkfv bgkljmf_glZ b khdjZlbl
kem [u
Dh]^Z ijhk_jeb\Z_fh_ hl_jklb
gh\blky kd\haguf gZ bgkljmf
Tha^_ckl\m_l agZqbl_evgh_ mkbeb
m^_j`b\Zcl_ bgkljmf_gl b-[m^v
jh`gu_ dh]^Z k_jeh gZqbgZ_l ij
kd\haguf h[jZ[Zlu\Z_fmx ^_lZev
AZklj\vr_ k_jeh fh`gh \ugmlv
ijhklh]h l_j_dexq_gby j__jkb\gh]h
dexqZl_ey gZ h[jZlgh_ \jZs_gb_
oh^hf H^gZdh bgkljmf_gl-fh`_l
gmlvky \ h[jZlghf gZijZ\e_gbb k
[ukljh _keb _]h g_ ^_j`Zlv dj_idh
<k_h_h mfh
Tf^Z_fhc ^_lZeb \ lbkdZo beb ih
aZ`bfghf mkljhckl_
Bal_lZcl_ k_je_gby \ fZl_jbZe_
ihZ[Z_l_ fh]ml-bf_lv
ijb_klb d aZdebgb\Zgbx beb
ZljhgZ
dhjhgZuc

L_oh[kem`b\Zgb_ b k_j\bk

L_oh[kem`b\Zgb_ b hqbkldZ
y l_j_^ ex[ufb fZgbimeypbyfb k
we_dljhbgkljmf_glhf \ulZkdb\Zcl_
rl_ik_ev ba jha_ldb
y >ey h[_ki_q_gby dZq_kl_gghc b [_a
hiZkghc jZ[hlu kh^_j`bl_ we_dljhbg
kljmf_gl b _glbeypbhggu_ ijhj_ab \
qbklhl_
?keb lj_[m_lky ihf_gylv rgmj- \h bal_ Z
gb_ hiZkghklb h[jZsZcl_kv gZ nbjfm 3 , 7
beb \ Z\lhjbah\Zggmx k_j\bkgmx fZkl_j
kdmx ^ey we_dljhbgkljmf_glh\ 3 , 7


OjZg_gb_ b ljZgkihjlbjh\dZ

OjZgbl_ bgkljmf_gl \ aZdjuluo ihf_s_gb
yo k _kl_kl_gghc _glbeypb_c \ miZdh\d_
ijb l_fi_jZlmj_ \ha^moZ hl ƒK ^h ƒK b
\eZ`ghklb \ha^moZ g_ [he__
LjZgkihjlbjh\Zlv ijh^mdpbx fh`gh ex
[uf \b^hf aZdjulh]h ljZgkihjlZ \ miZdh\
d_ ijhba\h^bl_ey beb [_a g__ k khojZg gb
_f ba^_eby hl f_oZgbq_kdbo ih\j _`^_gbc
Zlfhkn_jguo hkZ^dh\ l_j_^ ljZgkihjlb
jh\dhc ba\e_dbl_ Zddmfmeylhj b hkgZkldm
ba bgkljmf_glZ

MlbebaZpby

Hlkem`b\rb_ k\hc kjhd we_dljhbg
kljmf_glu ijbgZ^e_`ghklb dexqZgb_f
dh\dm ke_^m_l k^Z\Zlv gZ \lhjbqgh_
q_kdb qbklmx i_j_jZ[hldm hloh^h\
Mlbebabjmcl_ we_dljhbgkljmf_glu b bo
hl [ulh\h]h fmkhjZ

JZkrbnjh\dZ ^Zlu ba]hlh\e_gby ba^_eby



>ZlZ ba]hlh\e_gby ba^_eby aZrbnjh\ZgZ \
k_jbcghf ghf_j_ gZi_qZlZgghf gZ dhji m
k_ bgkljmf_glZ l_j\u_ pbnju h[hagZ
qZxl]h^ \uimkdZ ke_^mxsb_ f_kyp

MKEH<BY =:J:GLBCGH=H H; KEM@B<:GBY

GZklhys__]ZjZglbcgh_ k\b^_l_evkl\h
y\ey_lky _^bgkl_gguf ^hdmf_glhf ih^
l_j`^Zxsbf \Zr_ ijZ\h gZ [_kieZlgh_
]ZjZglbcgh_ h[kem`b\Zgb_ -;_a ij^ty\
e_gby ^Zggh]h k\b^_l_evkl\Z ij l gabb
g_ ijbgbfZxlky < kemqZ_ ml_jb beb ihjqb
]ZjZglbcgh_ k\b^_l_evkl\h g_ \hkklZg Z\
eb\Z_lky

=ZjZglbcguc kjhd mdZaZg \ ]ZjZ
k_jlbnbdZl_ < l_q_gb_]ZjZglbcg
dZ k_j\bkgZy kem`[Z [_kieZlgh m
ijhba\h^kl_ggu_ ^_n_dlu b ijhba
aZf_gm ^_lZe_c \ur_^rbo ba k
\bg_ ba]hlh\bl_ey GZ i_jbh^]ZjZ
dl_fhglZ wd\b\Ze_glguc bkijZ\guc b
f_gl g_ ij_^hkklZ\ey_lky AZf_
^_lZeb i_j_oh^yl \ kh[kl_gghklv
k_j\bkZ
DhfiZgby J , L g_ g_k_l hl_lkl
aZ \j_^ dhlhjuc fh`_l [ulv ijbqbg_
jZ[hl_ k we_dljhbgkljmf_glhf
<]ZjZglbcguc j_fhgl bgkljmf_g
gbfZ_lky \ qbklhf \b^_ ijb h[yaZl_
gZebqbb gZ^e_`Zsbf h[jZahf hnhj
guo ^hdmf_glh\ gZklhys_]h]ZjZg
k\b^_l_evkl\Z]ZjZglbcgh]h lZehg
ghklvx aZiheg_ggufb iheyfb rl
lhj]h\hc hj]ZgbaZpbb b ih^ibkvx
l_ey
=ZjZglbcguc j_fhgl g_ ijhba\h^
ke_^mxsbo kemqZyo
ijb hlkmlkl\bb]ZjZglbcgh]h k\b
kl\Z b]ZjZglbcgh]h lZehgZ beb g_
ghf bo hnhjfe_gbb
kl_i_gv baghkZ ^bZf_ljZ dh
dhlhjZy ^\b]Zl_ey ij_\urZ_l -ff aZ
bexqZgb_f bgkljmf_glh\ k [_ks_l
Z\b]Zl_eyfb
h\ijb kh\f_klghf \uoh^_ ba kljhy y
kl\Z b we_dljh^\b]Zl_ey ijb h[m
beb hieZ\e_gbb i_j\bqghc h[fhldb
mhifZlhjZ k\Zjhqgh]h ZiiZjZlZ
gh]h beb imkdh aZjy^gh]h mkljh
hieZ\e_gbb \gmlj_ggbo ^_lZe_c
we_dljhgguo ieZl b ^jm]bo kemqZy
keb]ZjZglbcgh k\b^_l_ev
lZehg g_ ijbgZ^e_`Zl ^Zgghfm we_
kljmf_glm beb g_ khhl_lkl\m_l
e_gghfm ihklZ\sbdhf h[jZapm
ih hkhq_gbb kjhdZ]ZjZglbb
ijb ihiuldZo kZfhklhyl_evgh]h \k
beb ij fhglZ we_dljhbgkljmf_glZ
pbnju
jZglbcghc fZkl_jkdhc
\g k_gby dhgkljmdlb\guo baf
kfZadb bgkljmf_glZ \ ]ZjZglbcguc
h q_f k\b^_l_evkl\mxl gZijbf_j a
gZ_ebp_\uo qZklyo dj_i_`Z dh
^_lZe_c
ijb bkihevah\Zgbb we_dljhbgkl
\ ijhba\h^kl_gguo beb bguo p_
aZgguo k ihemq_gb_f ijb[ueb Z lZ
\hagbdgh_gbb g_bkijZ\ghkl_c k\
k g_klZ[bevghklvx iZjZf_ljh\ we_d
lb ij_\urZxsbo ghjfu mklZgh\e_

=HKL rZlmgZ b ihjrg_\h]h iZevpZ
ijb g_ijZ\bevghc wdkiemZlZpbb gZkl\evgb_ b \gmlj_ggb_ aZ]j
ah\Zgbx we_dljhbgkljmf_glZ-g_piZhjZgZgZgZlj_sbgu ih\j_`^_gby \h
q_gbx mdZaZgghfm \ bgkljm-dphb_ih\ wjdkje_mk_ wdkiemZlZpbb be
ZlZpbb mklZgh\db gZ we_dljhbgkljmfh_glbg_
ij_^gZagZq_gguo aZ\h^hf ba]hlhij\ljZe[hf_ we_dljhbgkljmf_glhf k
gZkZ^hd ^hihegbl_evguo ijbkih]kmhed_hgcbo aZdebgb\Zgb_f hkgZk
b li k\b^_l_evkl\mxl aZ^bju baf_g_gb
ijb f_oZgbq_kdbo ih\j_`^-gbhyo ld_hfjii_mjZlmju mihjguo b ijb`
kZ k_l_\h]h rgmjZ b ijb ih\j_rZ^c[gbaZobfgh]h iZljhgZ \uoh^Z ba
\ua\Zgguo \ha^_ck\byfb Z]jj_k^kmbdMghjuZo
kj_^kl\ b \ukhdbo b gbadbo llfhin_bjeZdhljbq_kdh_ h[kem`b\Z-gb_ w
ihiZ^Zgbb bghjh^guo ij_^f_l-h\ bgkgjlmf_glZ qbkldZ ijhfu\dZ
eypbhggu_ j_r_ldb we_dljhbgkaZmffggZlZiuevgbdh\ ihjrg_\uo b
Z lZd`_ ijb ih\j_`^_gbyo gZklmgbVr_beovguo dhe_p \ ]ZjZglbcguo
j_amevlZl_ g_ijZ\bevgh]h o-jZgy\eby_lkyhjeZlghc mkem]hc
jhaby f_lZeebq_kdbo qZkl_c Kjhd kem`[u ba^_eby khklZ\ey_l
ijb _kl_kl_gghf baghk_ ^_lZkejhd owjeZgdgby ±]h^Z G_ j_dhf_
ljhbgkljmf_glZ \ j_amevlZl_ ^ebbwdekvjemmcZlZpbb ih bkl_q_gbb e
wdkiemZlZpbb hij_^_ey_lky ih gjbyakgZ^dZZd ba]hlh\e_gby dhlhjZy
iheghc beb qZklbqghc \ujZ[hldk_jjbkmghkfZghf_j_ gZ wlbd_ld_ bgklj
kbevgh]h aZ]jyag_gby j`Z\qbgu[_kaZjjm^bZpbl_evghc ijh_jdb- hij_
\gmljb we_dljhbgkljmf_glZ hljZgh[hlZ^gZlhuc\uimkdZ kfhljbl_ jZg__
kfZadb \ j_^mdlhj_ \h^kl_ ihevah\Zl_ey
ijb \hagbdgh_gbb ih\j_`^_gbeH \\kayfabguo gZjmr_gbyo baek
k g_kh[ex^_gb_f ij_^mkfh-lj_ugruomkegh\bc]ZjZglbcgh]h h[kem`
kljmdpb_c mkeh\bc wdkiemZlZpbeZ^kfevjeZ\mhh[sZ_lky ihke_ ijh\
©MdZaZgb_ ih l_ogbd_ [_ah-iZkgbZlgh^klbgb \ k_j\bkghf p_glj_
kljmdpbb e_p bgkljmf_glZ ^h_jy_l ijh\
ijb ih\j_`^_gbb ba^_eby \ke_^kbZlggh_klbdb \ k_j\bkghf p_glj_
kh[ex^_gby ijZ\be ojZg_gby-b hjlZgmkkhlb_
lbjh\db AZij_sZ_lky wdkiemZlZpby we_dlj
ijb kbevghf \gmlj_gg_f aZ]-jyafg_gbb bjgb ijhy\e_gbb ijbagZdh\
kljmf_glZ r_ggh]h gZ]j_\Z bkdj_gby ZlZd`
ijb jZ[hl_ k i_j_]jmadhc-[_gja\hmgkhjghc qZklb >ey \uykg_gby
f_glZ baf_g_gbb p_lZ qZrdbg_bbkfmZh\guhklb ihdmiZl_ex k-e_^m
kp_ie_gby \ j_amevlZl_ i_j_]j_\Zblvky \ ]ZjZglbcgmx fZkl_jkdmx
ijb h[ju_ rgmjZ klZjl_jZ ijb mGk_ebk\ihjZ\ghklb \ua\Zggu_ g_k\h_\
bkijZ\ghklb hklZevguo ^_lZe_c gjmkdaZhf]hghc m]hevguo s_lhd ^
mkljhckl\Z mkljZgyxlky aZ kq_l ihdmiZl_ey
gZ \k_ \b^u jZ[hl \uihegy_fu_ i-jZjZ_glby g_ jZkijhkljZgy_lky gZ
jbh^bq_kdhf l_ogbq_kdhf h[kemkfbgZgub bijbgZ^e_`ghklb Zdk_k
j_]mebjh\db qbkld_ aZf_g_hkjZZkolhd^Zguogzijbf_j Zddmfmeylhju
fZl_jbZeh\ b ^j gh`b k_jeZ [mju iZljhgu- p_i
gZ g_bkijZ\ghklb \hagbd-rb_^hqjd_bampeZvg]h\u_ aZ`bfu rbgu we
lZl_ gZjmr_gby lj_[h\Zgbc gbZly j_Zgbye b dj_ie_gby]heh\db
wdkiemZlZpbb mklZgh\e_ggufjhiZkiihh^jhhfu rebnh\Zevguo b e_glh
ba^_eby GZijbf_j i_j_]j_\ fbZabgebmybevlju]heh\db r_klb]j
g_kh[ex^_gb_ lj_[h\Zgbc d-khkkZ\mgb_dgZZkZ^db b li
q_kl\m lhieb\ghc kf_kb ih\e_drbdu\kuhjhbagZrb\Zxsb_ky ^_l-Zeb
ba kljhy ihjrg_\hc]jmiiu [_amk_ejh\gmujfhevgu_ s_ldb ijb\h^gu_
ijbagZdhf wlh]h y\ey_lky aZe_]kZbe_vghbjdb aZsblgu_ dh`meb g
g_\h]h dhevpZ b beb gZebqbsbpZjjZe-bgbb gZijZ\eyxsb_ j_a
ihl_jlhkl_c gZ \gmlj_gg_c ih\mjeghghkgbby ih^rbigbdb am[qZlu
pbebg^jZ b ih_joghklb ihjrg-y jbZadjmer_kZ kl\heu e_glu lhjf-haZ
gb_ beb hieZ\e_gb_ hihjguo ih^dbjbgbdhku klZjl_jh\ ihjrg_\u_ dhe

l i

AZf_gZ bo \ l_q_gb_]ZjZglbcgh]h kjhdZ
y\ey_lky ieZlghc mkem]hc
rgmju iblZgby \ kemqZ_ ih\j_`^_gby
baheypbb < ^Zgghf kemqZ_ ihlj_[bl_ev
^he`_g [ulv m_^hfe_g b j_fhgl mkem]Z
ieZlgZy ^he`_g [ulv \uiheg-g ihke_ kh
]eZkby ihlj_[bl_ey ?keb ihlj_[bl_ev g_
kh]eZk_g gZ aZf_gm lh \ ex[hf j_fhgl_
wlh]h bgkljmf_glZ [m^_l hldZaZgh NZdl
hldZaZ ^he`_g [ulv aZnbdkbjh\Zg \ ]ZjZg
lbcghf lZehg_ beb d\blZgpbb k_j\bkgh]h
p_gljZ b ih^ibkZg \eZ^_evp_f

P.I.T. WARRANTY CERTIFICATE

Place of seal

Product Name_____

Product Serial Number ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘

Charger Serial Number ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘

Sale Date _____

Trade Organization Name _____

Dear customer!

7KDQN \RX IRU SXUFKDVLQJ WKH 3 , 7 WRRO DQG ZH KRSH W

In the process of manufacturing the P.I.T tools pass multilevel quality control, if nevertheless your product will need maintenance, please contact the authorized P.I.T service centers.

Attention!

:KHQ EX\LQJ DVN D VHOOHU WR FKHFN WKH FRPSOHWHQHVV
:DUUDQW\ &HUWL¿FDWH WKH :DUUDQW\ &DUG WKH ER[HV VH
VHDO RI WKH WUDGH RUJDQL]DWLRQ LQ WKH *XDUDQWHH &H

Warranty

%\ WKLV :DUUDQW\ &HUWL¿FDWH 3 , 7 FRPSDQ\ JXDUDQWHH
nature.

In the event any of the above defects are detected during the warranty period, the specialized P.I.T. service centers shall repair the product and replace the defective spare parts free of charge.

The warranty period for P.I.T. electric machines is 12 months from the date of sale.

“The warranty maintenance terms acknowledged and accepted. The operability and completeness of the product are checked in my presence. No claims on quality and appearance.”

Buyer’s Signature_____ Surname (legibly) _____

Phone _____

=:J:GLBCGH? K<B>?L?EVKL<H G: BGKLJMF

GZbf_gh\Zgb_ ba^_ebyBBBBBBBBBBB
K_jbcguc ghf_j ba^_eby‘‘‘‘‘‘‘

K_jbcguc ghf_j aZjy^gh]h m‘k‘l‘j‘h‘c‘k‘l‘Z‘‘‘‘

М.П.

>ZlZ ijh^Z`b ©BBBBBª BBBBBBBBBBBBBBBBBBB
GZbf_gh\Zgb_ lhj]h\hc hj]ZgbaZpbb
M\Z`Z_fuc ihdmiZl_ev

;eZ]h^Zjbf <Zk aZ ihdmidm bgkljmf_glZ J , L b gZ^__fky qlh <
k\hbf \u[hjhf
ljb g_h[oh^bfhklb h[kem`b\Zgby <Zr_]h ba^_eby h[jZsZcl_kv-\ Z\l
\bkgu_ p_glju J , L <k_ k_j\bkgu_ p_glju ij_^klZ\e_gu gZ kZcl_ Z

<gbfZgb_
ljb ihdmid_ lj_[mcl_ m ijh^Z\pZ ijh_jdb jZ[hlhkihkh[ghklb bgk
ie_dlghklb Z lZd`_ aZiheg_gby]ZjZglbcgh]h k\b^_l_evkl\Z]ZjZg
©AZihegyxlky ijh^Z\phfª b ijhklZgh\db i_qZlb lhj]h\hc hj]Zgba
k\b^_l_evkl_ b]ZjZglbcguo lZehgZo

=ZjZglby
GZ hkgh\Zgbb ^Zggh]h]ZjZglbcgh]h k\b^_l_evkl\Z dhfiZgby J , L
^_n_dlh\ ijhba\h^kl_ggh]h oZjZdl_jZ
?keb \ l_q_gb_]ZjZglbcgh]h kjhdZ \ <Zr_f ba^_ebb h[gZjm`Zlky n
ki_pbZebabjh\Zggu_ k_j\bkgu_ p_glju J , L [_kieZlgh hlj_fhglbjn
gyl ^_n_dlgu_ aZiZkgu_ qZklb
=ZjZglbcguc kjhd gZ we_dljhbgkljmf_glu J , L khklZ\ey_l f_kyp

©K mkeh\byfb]ZjZglbcgh]h h[kem`b\Zgby hagZdhfe_g Z JZ[hlhk
ghklv ba^_eby ijh_j_gu \ fh_f ijbkmlkl\bb lj_l_gabc d dZq_kl\m
bf_xª

I h ^ i b k v i h d m i Z l _ e y B B B B B B B B B B B B B B B B B B B
\h BBBBBBBBBBBBBBBBBBBBBBBBB
L_e_nhgBBBBBBBBBBBBBBB

P.I.T. WARRANTY CARD

Name_____
Serial Number_____
Sale Date _____20__
Date of Receipt from Repair ____20__

P.I.T.

Name_____
Serial Number_____
Sale Date _____20__ Place of Seal
(Filled out by a Seller)
WARRANTY REPAIR CARD
Date of Acceptance for Repair _____20___
Application for Repair _____
Customer _____
Phone (Address)_____
Cause of Application_____
Date of Receipt from Repair _____20__
The Tool is checked in my presence_____
(The Order shall be performed in a Service Center) (Signature)

Name_____
Serial Number_____
Sale Date _____20__
Date of Receipt from Repair ____20__

P.I.T.

Name_____
Serial Number_____
Sale Date _____20__ Place of Seal
(Filled out by a Seller)
WARRANTY REPAIR CARD
Date of Acceptance for Repair _____20___
Application for Repair _____
Customer _____
Phone (Address)_____
Cause of Application_____
Date of Receipt from Repair _____20__
The Tool is checked in my presence_____
(The Order shall be performed in a Service Center) (Signature)

Name_____
Serial Number_____
Sale Date _____20__
Date of Receipt from Repair ____20__

P.I.T.

Name_____
Serial Number_____
Sale Date _____20__ Place of Seal
(Filled out by a Seller)
WARRANTY REPAIR CARD
Date of Acceptance for Repair _____20___
Application for Repair _____
Customer _____
Phone (Address)_____
Cause of Application_____
Date of Receipt from Repair _____20__
The Tool is checked in my presence_____
(The Order shall be performed in a Service Center) (Signature)

=:J:GLBCGUC L:EHG J L

P.I.T. LZehg ‹

GZbf_gh\Zgb_ BBBBBBBBBBBBBBBBBBBBBBBBB
K_jbcguc ghf_jBBBBBBBBBBBB
>ZlZ ijh^Z`b ____ F_________20__ F_klh i_qZlb
AZihegy_lky ijh^Z\phf beb rlZfiZ
D:JL: =:J:GLBCG2=2 J?FHG:
>ZlZ ijb_fZ j_fhgl BBBBBBB BBB
AZy\dZ gZ j_fhgl BBBBBBBBBBBBBBBBBBBB
AZdZaqbd BBBBBBBBBBBBBBBBBBBBBBBBBBBBBB
L_e_nhg Z^j_k BBBBBBBBBBBBBBBBBBBBBBBBB
IjbqbgZ h[jZs_gbyBBBBBBBBBBBBBBBBBBBBBB
>ZlZ ihemq_gby hl j_fhglZ BBBBBBBBBBBB BB
Bgkljmf_gl ijh_j_g \ fh_f ijbkmlkl\bb BBBBBBBBBB
AZdZa aZihegy_lky \ K_j\bkghf P_glj_ Ih^ibkv

GZbf_gh\Zgb_ BBBBBBBB
K_jbcguc ghf_jBBBBB
>ZlZ ijh^Z`b BBBBBBBBBBB
>ZlZ ihemq_gby hl j_fhglZ BBBBBBB

P.I.T. LZehg ‹

GZbf_gh\Zgb_ BBBBBBBBBBBBBBBBBBBBBBBBB
K_jbcguc ghf_jBBBBBBBBBBBB
>ZlZ ijh^Z`b ____ F_________20__ F_klh i_qZlb
AZihegy_lky ijh^Z\phf beb rlZfiZ
D:JL: =:J:GLBCG2=2 J?FHG:
>ZlZ ijb_fZ j_fhgl BBBBBBB BBB
AZy\dZ gZ j_fhgl BBBBBBBBBBBBBBBBBBBB
AZdZaqbd BBBBBBBBBBBBBBBBBBBBBBBBBBBBBB
L_e_nhg Z^j_k BBBBBBBBBBBBBBBBBBBBBBBBB
IjbqbgZ h[jZs_gbyBBBBBBBBBBBBBBBBBBBBBB
>ZlZ ihemq_gby hl j_fhglZ BBBBBBBBBBBB BB
Bgkljmf_gl ijh_j_g \ fh_f ijbkmlkl\bb BBBBBBBBBB
AZdZa aZihegy_lky \ K_j\bkghf P_glj_ Ih^ibkv

GZbf_gh\Zgb_ BBBBBBBB
K_jbcguc ghf_jBBBBB
>ZlZ ijh^Z`b BBBBBBBBBBB
>ZlZ ihemq_gby hl j_fhglZ BBBBBBB

P.I.T. LZehg ‹

GZbf_gh\Zgb_ BBBBBBBBBBBBBBBBBBBBBBBBB
K_jbcguc ghf_jBBBBBBBBBBBB
>ZlZ ijh^Z`b ____ F_________20__ F_klh i_qZlb
AZihegy_lky ijh^Z\phf beb rlZfiZ
D:JL: =:J:GLBCG2=2 J?FHG:
>ZlZ ijb_fZ j_fhgl BBBBBBB BBB
AZy\dZ gZ j_fhgl BBBBBBBBBBBBBBBBBBBB
AZdZaqbd BBBBBBBBBBBBBBBBBBBBBBBBBBBBBB
L_e_nhg Z^j_k BBBBBBBBBBBBBBBBBBBBBBBBB
IjbqbgZ h[jZs_gbyBBBBBBBBBBBBBBBBBBBBBB
>ZlZ ihemq_gby hl j_fhglZ BBBBBBBBBBBB BB
Bgkljmf_gl ijh_j_g \ fh_f ijbkmlkl\bb BBBBBBBBBB
AZdZa aZihegy_lky \ K_j\bkghf P_glj_ Ih^ibkv

GZbf_gh\Zgb_ BBBBBBBB
K_jbcguc ghf_jBBBBB
>ZlZ ijh^Z`b BBBBBBBBBBB
>ZlZ ihemq_gby hl j_fhglZ BBBBBBB

P.I.T.

Media account

pit_global PIT Global YouTube PIT Global

bod@pit-tools.com www.pit-tools.com