
OPERATION MANUAL
ИНСТРУКЦИЯ ПОЛЬЗОВАТЕЛЯ

P.I.T.

PBO20H-450A



CORDLESS BLOWER

АККУМУЛЯТОРНАЯ ВОЗДУХОДУВКА

20V ONE POWER

Please read the instruction manual carefully before use!
Пожалуйста, внимательно прочтите инструкцию перед использованием!


4
5
3
6
1
2
P.I.T.

Fig.2



Fig.3



Fig.4




Fig.5



English

Safety instructions

Safety instructions for the electric blower.



Read all safety instructions and instructions. Omission of directions and safety instructions can result in HOHFWULF VKRFN ¿UH DQG VHULRXV LQMXU\

Safety precautions for electric blower

7R DYRLG ILUH HOHFWULF VKRFN and personal injury observe the safety instructions. Read these guidelines:

Workplace safety

- The work area must be clean and well lit. Litter and poor lighting can cause accidents.
- Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases, or dust. Power tool operations generate sparks that can ignite dust or gases.
- Keep children or bystanders away from the work area when operating a power tool. Do not distract yourself while working as this will result in loss of control of the power tool.

Electrical safety

- Power tool plugs must match the outlet. Never make any modifications to the outlet. Do not use adapters when using a grounded power tool. Unmodified outlets and plugs reduce the risk of electric shock.
- Avoid body contact with grounded surfaces such as pipes, radiators, ra - diators, and refrigerators. Body contact ZLWK HDUWKHG REMHFWV LQFUHDVHV WKH ULVN RI electric shock.
- Do not expose power tools to rain or moisture. Water entering a power tool will increase the risk of electric shock.
- Handle the power cord with care; never use the power cord to carry, move or unplug the power cord. Keep cord away from heat, oil, sharp edges, and moving parts. Damaged or tangled power cords increase the risk of electric shock.
- When using the power tool outdoors, use an extension cord that is suitable for this purpose. Using the correct cord reduces the risk of electric shock.
- When operating the power tool in a damp place, connect the power tool through a residual current device. The use of a residual current device (RCD) reduces the risk of electrical shock.

Personal safety

- Be careful when using a power tool, observe what you are doing and use common sense; do not use a power tool while you are tired or under the influ - ence of drugs, alcohol or medication. Even momentary inattention when using a SRZHU WRRO FDQ UHVXOW LQ
- Use personal protective equipment. Be sure to wear safety glasses. Personal protective equipment such as a respirator, non-slip safety shoes, hard hat or ear- PX‡V ZKHQ XVHG XQGHU DSS WLRQV FDQ UHGXFH WKH ULV
- Do not accidentally turn on the device. Make sure the switch is in the off po - sition before connecting the tool to a power source and / or battery, lifting or carrying the tool. Carrying a power tool ZLWK \RXU ¿QJHU RQ WKH VZ power to an instrument with the switch on, may result in an accident.
- Remove all adjusting tools and wrench - es from power tool before operating power tool. /HDYLQJ D ZUHQFK RU wrench attached to a rotating part could FDXVH LQMXU\
- Do not stretch while using the device; always maintain a stable position and balance. This will allow better control of the power tool in unexpected situations.
- Dress appropriately. Do not wear loose clothing or jewelry. Keep your hair, clothing and gloves away from rotating parts at all times. /RRVH FORWKLQJ or long hair can be caught in the moving parts of the device.
- If there are devices for connecting a dust collector or hood, make sure they are connected and used correctly. Using a dust bin reduces the likelihood of dust risks.
- Good knowledge of power tools, gained as a result of their frequent use, should not lead to self-confidence and disre - gard for safe handling of power tools. One careless action in a fraction of a sec- RQG FDQ UHVXOW LQ VHULRX
- ATTENTION! In the event of an interruption in the operation of the power tool due to a complete or partial loss of power supply or damage to the power control circuit, set the switch to the off position, making sure that it is not blocked (if any). Discon-

nect the mains plug from the socket or remove the removable battery. This prevents an uncontrolled restart.

- 4XDOL¿HG SHUVRQQHO LQ DFFRUGDQFH ZLWK WKLV manual means persons who are familiar ZLWK WKH DGMXVWPHQW sioning and maintenance of power tools.
- Only persons over 18 years of age who have read the technical description, operating instructions and safety rules are allowed to work with power tools.
- The product is not intended for use by persons (including children) with reduced physical, sensory or mental capabilities, or lack of life experience or knowledge, unless they have been supervised or instructed in the use of power tools by a person responsible for their safety..

Power tool use and care

- Do not use excessive force on the pow - er tool. Use the right tool for the job you are doing. The right power tool will do WKH MRE EHWWHU DQG VDIHU DW WKH UDWH it was designed for.
- Do not use a power tool with a defective switch. Any power tool with a defective switch is dangerous and must be repaired.
- Always disconnect power tool and / or battery before making adjustments, changing accessories, or storing power tool. Such preventive measures reduce the risk of starting the power tool accidentally.
- Store power tools out of the reach of children and do not allow persons un - familiar with the operation of the tool or reading these instructions to operate the power tool.
  Power tools are dangerous in the hands of inexperienced users.
- Service power tools. Check for align - ment, deformation of moving parts, breakage of any part, or other defects that could affect the operation of the power tool. If the instrument is dam - aged, have it repaired before use. A large number of accidents result from poor power tool maintenance.
- Use the power tool, accessories, attach - ments and attachments in accordance with these instructions and for the pur - pose for which it was designed, taking into account the conditions and type of work to be performed. Use of the power tool for purposes other than those intended may result in a hazardous situation.

Battery tool use and care

- The battery is not fully charged at the time of delivery. To ensure full battery performance, fully charge the battery be- IRUH ¿UVW XVH
- Only use the battery in combination LQVWDOODWLRQ EROBIS with your P.I.T. This is the only way to prevent dangerous battery overload.
- Charge batteries only with chargers recommended by the manufacturer. A charger designed for certain types of EDWWHULHV PD\ SUHVHQW D used with other batteries.
- 8VH RQO\ WKH VSHFL¿HG EDW er tools. Use of other batteries may result LQ SHUVRQDO LQMXU\ DQG ¿U
- Make sure the tool is switched off be - fore inserting the battery. Inserting a rechargeable battery into a powered tool may result in an accident.
- &KHFN WKH EDWWHU\ IRU ¿UP WZR OHYHOV RI ¿[DWLRQ

Important safety instructions for working with the battery pack.

WARNING: Use only original P.I.T. Use of batteries not manufactured by P.I.T. or batteries WKDW KDYH EHHQ PRGL¿HG PD H[SORVLRQ ILUH SHUVRQDO damage. This will also automatically void the P.I.T. on the P.I.T. tool and charger.

- Before using the battery pack, read all instructions and warning labels on the charger, battery pack, and tools pow - ered by the battery pack.
- Do not disassemble the battery pack.
- Do not drop or hit the battery pack.
- Do not use a damaged battery pack.
- If the operating time of the battery pack is significantly shortened, stop using it immediately. Otherwise, the unit may overheat, resulting in burns and even an explosion.
- If electrolyte gets into your eyes, rinse them with plenty of clean water and seek medical attention immediately. This can lead to vision loss.
- Do not short the contacts of the battery pack with each other:

(1) Do not touch the contacts with any con- GXFWLYH REMHFWV

(2) Do not store the battery pack in a con- WDLQHU ZLWK RWKHU PHWDO R coins, etc.

(3) Do not expose the battery pack to water or rain. Shorting the contacts of the battery pack

together can cause high current, overheating, possible burns, and even breakage of the pack.

- y Do not store the tool and battery pack where the temperature can reach or ex - ceed 50 °C (122 °F).
- y Do not throw the battery pack into a fire, even if it is severely damaged or completely out of order. The battery SDFN PD\ H[SORGH LI H[SRVHG WR ¿UH
- y Gas may be released if the battery is damaged or misused. Provide fresh air and if you have any complaints, consult a doctor. Gases can cause respiratory irritation.
- y Clean the battery ventilation slots from time to time with a soft, dry and clean brush.
- y Charge the battery pack without com - pletely discharging it. Be sure to stop using the tool and charge the unit if you notice a decrease in tool power.
- y Never recharge a fully charged battery pack. Overcharging shortens battery life.
- y Charge the battery pack at room tem - perature. Allow a hot battery pack to cool before charging.
- y Charge the lithium-ion battery pack if you will not use the tool for a long time (more than six months).
- y Do not open the battery, otherwise there is a danger of a short circuit.
- y Protect the battery from high tempera - tures, such as prolonged exposure to WKH VXQ ¿UH ZDWHU DQG PRLVWXUH 7KHUH is a risk of explosion.
- y Store the battery between 0 and 45°C. Do not leave the battery in the car in summer.
- y The supplied lithium-ion batteries must be used in accordance with the require - ments of the dangerous goods legisla - tion. For commercial shipments, such as by a third party or freight forwarder, special warnings and labels must be applied to the packaging. Be sure to consult with a Hazardous Materials Specialist when preparing your device for shipping. Also observe local requirements and regulations. They may be stricter. Cover or secure open contacts and pack the battery so that it does not move around in the package.
- y Follow local regulations regarding the disposal of the battery pack.

Safety instructions for air blowers

:$51,1* 7R UHGXFH WKH U-LVN R tric shock, or injury:

- y Do not leave appliance when plugged in. Unplug from outlet when not in use and before servicing.
- y WARNING: To Reduce the Risk of Electric Shock - Do not use on wet surfaces. Do not expose to rain. Store indoors.
- y Do not allow to be a toy. Close attention is necessary when used by or near children.
- y Use only as described in this manual. Use only manufacture's recommended attachments.
- y Do not use with damaged cord or plug. If appliance is not working as it should, has been dropped, damaged, left outdoors, or dropped into water, return it to a service center.
- y Do not pull or carry by cord, use cord as a handle, close a door on cord, or pull cord around sharp edges or comers. Do not run appliance over cord. Keep cord away form heated surfaces.
- y Do not unplug by pulling on cord. To unplug, grasp the plug, not the cord.
- y Do not handle plug or appliance with wet hands.
- y 'R QRW SXW DQ\ REMHFW LQ not use with any opening blocked; keep free of dust, lint, hair, and anything that PD\ UHGXFH DLU ÀRZ
- y Keep hair, loose clothing, fingers, and all parts of body away form openings and- moving parts.
- y 7XUQ R‡ DOO FRQWUROV EHIR
- y Use extra care when cleaning on stairs.
- y 'R QRW XVH WR SLFN XS ÀDP bustible liquids, such as gasoline, or use in areas where they may be present.
- y $OZD\V WXUQ R‡ WKLV DSSOL necting or disconnecting either hose or motorized nozzle.
- y Do not pick up anything that is burning or smoking, such as cigarettes, matches, or hot ashes.
- y Recharge only with the charger specified by the manufacturer. A charger that is suitable for one type of battery pack may create a risk of frre when used with another battery pack.
- y 8VH SRZHU WRROV RQO\-ZLWK ignated battery packs. Use of any other EDWWHU\ SDFNV PD\ FUHDWH DQG ¿UH

y When battery pack is not in use, keep it away from other metal equipment like paper clips, coins, keys, nails, screws or other small metal objects that can make a connection from one terminal to another. Shorting the battery terminals together may cause burns or a frre.
y Under abusive conditions, liquid may be ejected from the battery. If contact accidentally occurs, flush with water. If liquid contacts eyes, additionally seek medical help. Liquid ejected from battery may cause irritation or burns.

Description of product and services

Read all safety instructions and instructions. Omission of directions and safety instructions can result in electric shock, fire and/or serious injury.

Intended use

The cordless blower is designed to clean the area from small debris and foliage.
It has the functions of blowing and suction, which expands the capabilities of the device.
Thanks to the operation of electricity, the unit does not emit harmful emissions into the atmosphere, which allows it to be used indoors.

Components shown

The general view of the tool is presented on the page with illustrations.
1.Extension Tube
2.Blower Tube
3.Tube Release button
4.Speed Control Switch
5.Handle
Not all accessories illustrated or described are included as standard.

Specifications

Model	PBO20H-450A
Voltage	DC 20V
Max. air volume	110/180 m³/h
No-load Speed	12000/18000 r/min
Weight	1.1 Kg

Contents of delivery

Cordless blower	1pc
Blower Tube	2 pcs
Operation manual	1pc

Note

The text and numbers in this manual may contain technical errors and typographical errors.
Since the P.I.T. is constantly improving, the company reserves the right to make changes to the specifications and equipment specified here without prior notice.

Working with the tool

WARNING:

- Always be sure the tool is unplugged before adjustments or checks are made to the operation of the tool.

Assembling the blower tube

Before assembling the blower tubes(1), (2) be sure the speed control switch (4) is in "o" position.

Fit the blower tube to the motor housing as shown in ¿J Check that it is correctly secured.

WARNING! Do not attempt to operate or disassemble the tool when the blower tube is removed. The blower tube may cause injury during removal of the tube.

Note: before disassembling the blower tube, be sure the speed control switch (4) is in "o" off position. Press the release button(3), so that you can separate the tube.(Fig. 3) Cocked up the next part of the extension down blower tube(!), So that you can separate the down blower tube.(Fig. 3) Do not try to separate the tubes by force or by using tools.

WARNING! The charger and battery pack are specially designed to worktogether so do not attempt to use any other devices.

Never insert or allow foreign objects into your charger or battery pack connections because of an electrical failure and hazard will occur.

1.Before using your cordless blower
You must charge once before use.
2.Charging your battery pack
The Li-ion battery is protected against deep discharging. When the battery is empty, the protective circuit: The tool holder no longer rotates.
In a warm environment or after heavy use, the battery pack may become too hot to permitcharging. Allow time for the battery to cool down before recharging.
3.To remove or install battery pack (Fig. 4)
•Always move the Speed Control Switch (4) to the off position before installing the battery pack.
•To remove the battery pack, withdraw it from the tool while pulling the Battery Release Button (7) down.
•To insert the battery pack, groove along the handle and insert in the full position, until the Battery Release Button (7) bounce back to

normal position again.
4.Starting/stopping (Fig. 5)
Starting
Move the Speed Control Switch (4) to the “1” On position.
Stopping
0RYH WKH 6SHHG &RQWURO 6ZLWFK WR WKH 2II position.
5. Using the blower
The blower is intended for residential use only.
Use the blower outdoors to move debris from hard surfaces. This blower is not designed to clear leaves from large grassy areas, or move wet, heavy debris.
User tips
- During operation, keep the air duct approximately 18-20cm above the ground.
Move from side to side, as if you were sweeping, gradually moving forward.
Debris/leaves to be blown away must be in front of you
Caution!

- After blowing the debris/leaves into a pile, it is easy to dispose of the pile.
'R QRW EORZ KDUG REMHFWV VXFK DV QDLOV bolts, or rocks.
- Do not operate the blower near bystanders or pets.
- Use extra care when cleaning debris from stairs or other tight areas.
- Wear safety goggles or other suitable eye protection, long pants, and shoes.

0DLQWHQDQFH VHUYLFH

Maintenance and cleaning
ATTENTION! Make sure the tool is switched off and unplugged before checking or performing maintenance.

- Every time after finishing work, it is recommended to clean the body of the instrument and the ventilation openings from dirt and dust with a soft cloth or napkin. It is recommended to remove stubborn dirt with a soft cloth dampened with soapy water. It is unacceptable to use solvents to eliminate contamination: gasoline, alcohol, ammonia solutions, etc. The use of solvents can damage the body of the instrument.
- The tool does not require additional lubrication.

Service

y+DYH \RXU SRZHU WRRO UHSDLUHG RQO\ E\ TXDOLI ified personnel and only with original spare parts. This ensures the safety of the power tool.A list of authorized service centers can be viewed on the official P.I.T. website. link https://pittools.ru/servises/


Storage and transportation

Store the instrument in closed rooms with natural ventilation in packaging at an air temperature of 0 °C to + 50 °C and an air humidity of no more than 80%. Products can be transported by any type of closed transport in the manufacturer’s packaging or without it, while preserving the product from mechanical damage , atmospheric precipitation. Remove the battery and replacement tool from the tool before transporting it.

Disposal

Take power tools, batteries, accessories and packaging to an environmentally friendly recovery facility.
Do not dispose of power tools and rechargeable batteries / batteries with household waste!

Product serial number interpreta - tion serial number



The date of manufacture of the product is encoded in the serial number printed on the ERG\ RI WKH WRRO 7KH ¿UVW year of issue, the next 2 digits indicate the month.

TERMS OF WARRANTY SERVICE

To customers (users) of warranty service:
1. This warranty certificate is the only docu- PHQW WKDW FRQ¿UPV \RXU ULJ service. If this proof is not presented, no FODLPV ZLOO EH DFFHSWHG :D cannot be recovered if lost or damaged.
2. It is required to provide a valid and legal document for purchasing the product. The document must have the name or seal of the sales company; at the same time, state the full model name of the purchased P.I.T. product, the serial number on the nameplate of the fuselage, and the date of purchase, and the required warranty. The whole machine and its accessories.
The warranty period:
1. The warranty period of the product is 12 months from the date of sale. During the warranty period, the service department will eliminate manufacturing defects free of

charge and replace the parts that fail due to the manufacturer's fault. In warranty repair, an equivalent operable product is not provided. Replaceable parts become the property of the service provider.

2. The wear degree on the diameter of the motor rotor commutator is less than 0.4 mm (except for brushless motor tools), and the internal damage caused by the quality of the tool belongs to the warranty.

The following situations occur during the warranty period, which is not covered by the warranty:

1. In the absence of any valid legal documents invoices such as and warranty cards to prove the date of purchase.

2. Damage caused by natural wear and overload. (For example, motor rotor and stator failure caused by overload, scorching or melting of the primary winding of the welding machine transformer, charging or starting the charging device, melting of internal parts, burning of electronic circuit boards, etc.)

3. The casing and power cord are mechanically damaged, as well as damage caused by corrosive media and high and low temperature interference objects entering the network of the motor, and damage caused by improper storage (corrosion of metal parts);

4. Damage caused by improper carrying, transportation and storage by users.

5. Products that are opened, repaired, replaced or modified by users themselves

6. Any damage caused by indiscriminate use, beyond the scope of use of the tool, and not in accordance with the instructions for use and maintenance. (see chapter "Safety Precautions" in the manual);

7. The damage caused by the following situations is not guaranteed due to improper use and non-quality problems:

(1) When the power tool is running at high speed, use the braking device to forcibly stop the rotation.

(2) Excessive pressure is applied to the tool during the use of the tool.

(3) Use the tool outside the scope of its purpose and capabilities.

(4) Damage caused by the tool working in a dusty environment for a long time without timely maintenance of the tool.

(5) Change the rotation direction of the work head before the tool stops completely.

(6) Shock the battery or charger and replace the plug of the charger without permission, causing damage to the battery or charger.

(7) Damage caused by two-stroke gasoline tools not being fueled in the correct proportions.

The warranty does not include:

1. Replacement of accessories (accessories and components) such as batteries, discs, blades, drills, drills, chucks, chains, sprockets, collet clamps, guide rails, tension and fastening elements, dresser heads, grinders And belt sander base machine, hexagonal head, etc.;

2. Wearing parts, such as: carbon brushes, transmission belts, seals, protective covers, guide rollers, guide rails, rubber seals, bearings, toothed belts and wheels, shanks, brake belts, starter ratchets and ropes, piston rings Wait.

The above accessories are replaced with paid services during the warranty period;

Jmkkdbc

MdZaZgby ih [_ahiZkghklb

MdZaZgby ih l_ogbd_ _ [_ahiZkghklb ^ey Zddmfmeylhjghc \ha^moh^m\db



ljhqlbl_ \k_ mdZaZgby b bgkljmdpbc ih l_ogbd_ [_ahiZkghklb ^ey Mims_gby \ hlghr_gbb mdZaZgbc ih bgkljmdpbc ih l_ogbd_ [_ahiZkghklb ^ey klZlv ijbqbghc ihjZ`_gby we_dljbq_kdbf lhdhf ih`ZjZ b ly`_euo ljZ\f

L_ogbdZ [_ahiZkghklb ^ey ljbq_kdhc \ha^moh^m\db

<h ba[_`Zgb_ \ha]hjZgby m^ZjZ lhdhf ljZ\f kh[ex^Zcl_ ke_^mxsb_ lj_[h\Zgby

;_ahiZkghklv \ f_kl_ \uiheg gby jZ[hl

- y JZ[hq__ f_klh ^he`gh [ulv qbkljmf b ohjhrh hk_s_gbZ b iehoh_ hk_s_gb_ fh]ml-klZlv ghc g_kqZklguo kemqZ_\
- y G_ ihevamcl_kv we_dljh-bgkljmf_glhf \h \aju\hhiZkghc Zlfhkn_ gZijbf_j \ ijbkmlkl\bb e_]dh \hk ieZf_gyxsboky `b^dhkl_c beb iuebjb jZ[hl_ we_dljh-bgkljmf_glhf \hagbdZxl bkdju dhlhju ijb_klb d \hkieZf_g_gbx iueb]Zah\
- y ljb jZ[hl_ k we_dljhbgkljmf_glhf g_ ^himkdZcl_ ^_l_c beb ihklhjhg gbo d f_klm \uiheg_gby jZ[hl hl\e_dZcl_kv \h \j_fy jZ[hlu wlh ijb_^_l d ihl_j_ dhgljhey we_dljhbgkljmf_glhf

We_dljh[_ahiZkghklv

- y <bedZ we_dljhbgkljmf_glZ khhl_lkl\h\Zlv k_l_\hc jha-ld_ dh]^Z g_ \ghkbl_ gbdZdbo baf_g_gbyf \ dhgkljmdpbx jha_ldb ljb bkihevam ah\Zgbb we_dljhbgkljmf_glZ k aZa_fe_ggufb ih_joghk-lyfb Jha_ldb b \bedb g_ ih^_j]Zcl_ dbfb dZd ljm[u jZ^bZlhju baf_g_gbyf kgb`Zxl jbkd ihjZ`_gby we_dljbq_kdbf lhdhf
- y Ba[_]Zcl_ dhglZdlZ mqZkldh\ aZa_fe_ggufb ih_joghk-lyfb dbfb dZd ljm[u jZ^bZlhju [ZlZdl_ l_eZ k aZa_fe_ggufb ij_^f_kZfb hlhie_gby b oheh^bevgbdhg m_ebqb\Z_lky jbkd ihjZ`_gby we_dljh q_kdbf lhdhf
- y G_ ih^_j]Zcl_ we_dljhbgkljmf_gl \ha^_ckl\bx ^h`^y beb lheZ]b iZ^Zgb_ \h^u \ we_dljhbgkljmf_gl ih \urZ_l jbkd ihjZ`_gby we_dljbq_kdbf lhdhf

:ddmjZlgh h[jZsZcl_kv kh rgmj ibl Zgby ^ey i_j_ghkdbl_ \ ha_lha_ldb JZkiheZ]Zcl_ rgmjZ kgb`Z_l jbkd ihjZ`_gby we_dljbq_kdbf lhdhf

ibl Zgby ^ey G bdh]^Z g_ bkihe

ibl Zgby ^ey i_j_ghkdbl_ \ ha_lha_ldb JZkiheZ]Zcl_ rgmjZ kgb`Z_l jbkd ihjZ`_gby we_dljbq_kdbf lhdhf

- y ljb bkihevah\Zgbb we_dl-jhbgkf_ghZ\g ihf_s_gby bkihevam^ebgbl_ev ih^oh^ysbc ^ey wlbe_c Bkihevah\Zgb_ khhl_lkl\mxrgmjZ kgb`Z_l jbkd ihjZ`_gby we q_kdbf lhdhf
- y Ykeb we_dljhbgkljmf_gl ijboh^b wdkiemZlbjh\Zlv \ kujhf f_kl_ ihdexqZcl_ we_dljhbgkljmf_gl q mkljhckl\h aZsblgh]h hldexq_ mf_g_gb_ mkljhckl\Z aZ-sblgh ldexq_gby kgb`Z_l jbkd we_dljbihjZ`_gby

Ebqgzy [_ahiZkghklv

- y ljb bkihevah\Zgbb we_dl-jhbgkf_ghZ\g ihf_s_gby bkihevam[m^vl_ [^bl_evgu ke_^bll_f qlh \u ^_eZ_l_ b jmdh-\h^kl_kv a^jZ\uf kfukehf G_ ihevamkv we_dljhbgkljmf_glhf _kebmklZeb gZoh^bl_kv ih^ \ha^_cklgZjdhlbdh\ Zedh]hey beb e_dZjkgu o ljh^ iZjZl-hZ`_ f]gh\_ggZg_\gbfZl_evghklv ijb bkihevalwe_dljhbgkljmf_glZ fh`_l ijb_k_jv_aghc ljZ\f_
- y Bkihevamcl_ kj_^kl\Z bg^b\b^m Gb ghc aZsblu H[yaZl_evgh gZ^_\aZsblu_ hqZbdb_ kj_^kl\Z bg^ib^mZevghc aZsblu dZd j_kibjZZy g_kdhevaysZy h[m\v dZgZbrgbdb bkihevam_fu_ \-khhlxsbo-mkeh\byo iha\heyxl kgbabih-ehdg_gby ljZ\fu
- y G_ ^himkdZcl_ kemqZcgh]h \dexmkejhckl\Z lj_`^_ q_f ih^kh_gyZv bgkljmf_gl d bklhqgbdm iblb_beb Zddmfmeylhjghc [Z-lZj__gbfZlv beb i_j_ghkblv bgkljmf_m[_bl_kv qlh i_j_dexqZl-_ev gbkly \ \udexq_gghf iheh`l_gbb j_ghkdZ we_dljhbgkljmf_glZ k i gZ-\udexqZl_e_ beb ih^ZqZ iblZbgkljmf_gl k \dexq_gguf-\udex

e_f fh`_l ijb\_klb d g_kqZklghfmkdZxmky ebpZ g_ fheh`_ -e_l qZx rb_ l_ogbq_kdh_ hibkZgb_ bgk

y l_j_^ \dexq_gb_f we_dlj-hbgkljmf_glZ hjwdkiemZlZpbb b ijZ\be-Z [_a f_glZ kgbfbl_ k g_]h \k_-j_]mkbjh

\hqgu_ bgkljmf_glu b]Z_q-gu_y beax^_eb_ g_ ij_^gZagZq_gh ^ey qb =Z_qguc beb j_]mebjh\hqguc hkZgby ebpZfb \dexqZy ^_l_c hklZ\rbcky aZdj_ie_gguf gZ \jZsZgufb nbabq_kdbfb qm\kl_ s_cky ^_lZeb fh`_l ijb_klb d ljZ\eb mfkl_ggufb kihkh[ghklyf

y ljb wdkiemZlZpbb mkljhckl\Z hgk_mlkl\bb m gbo `bag_ggh] lygbl_kv <k_]^Z khojZgycl_ mklbeqbagZgbc _keb hgb g_ gZoh \h_ iheh`_gb_ b jZ\ghW_khb-ih dhgljhe_f beb g_ ijhbgkljmdlbj a\hebl emqr_ mijZ\eylv we_dljhbgkljmf_glZ hjwdkiemZlZpbb b ijZ\be-Z [_a f_glhf \ g_ij_^\b^_gguo kblmZpbeybophf hl_lkl_gguf aZ-bo [_

y H^_\Zcl_kv khhl_lkl\mxsb-f h[jZhklv ahf G_ gZ^_\Zcl_ k\h[h-^gmkx ih^ `^m beb mdjZr_gby <Zrb \he hku h^_`^Z b i_jqZldb ^he`gu \k_]^Z gZoh^blvky gZ jZkklhygbb-hl \jZs-Z xsboky ^_lZeb \h[h^gZy h^_`^Z mdjZr_gby beb ^ebggu_ \hehkuf jmj ihiZklv \ ^\b`msb_ky ^_lZeb mkljhc kl\Z

y ?keb bf_xlky mkljhckl\Z-^ey jh^ dexq_gby iue_k[hjgbdZ be-b \ulv db m[_^bl_kv qlh hgb ih^kh_^bg_gu b ijZ\bevgh bkihevamcl_kv we_dljh-bgkljmf_glZ ah\Zgb_ iue_k[hjgbdZ kgb-Z_l \ jbvl ghklv \hagbdgh_gby jbkdh\ k\vaZgguo k iuevx

y Ohjhr__ agZgb_ we_dljhbgkljmf_g^ \uiheg_gb_f j_]mebjh\ lh\ ihemq_ggh_\ j_amevlZl_ qZkjh]h bo bkihevah\Zgby g_ ^he`gh ijb\h^ ^blv d kZfhm\_j_gghklb b-b]ghjbh \Zgbx l_ogbdb [_ahiZkgh-klb h[jZ s_gby k we_dljhbgkljmf_glZ \k_]^Z g_[j_`gh_ ^_ckl\b_ aZ ^hex k jmg^u fh`_l ijb_klb d k_jv_aguf ljZ\fZf

y <GBF:GB? < kemqZ_ \hagbdghjZ i_j_[hy \ jZ[hl_ we_dljhbgkljmf_glZ \ke_^kl\b_ ihegh]h beb qZklbqghjh ij_djZs_gby wg_j]hkgZ[`_gb_y beb ih\j_`^_gby p_ib mijZ\e_gby wg_j]h kgZ[`_gb_f mklZgh\bl_ \udexqZ_ \ iheh`_gb_ <ude m[_^b\rbkvy qlh hg g_ aZ[ehdbjh\Zg ijb _]h gZebgbb Hldexqbl_ k_l_\mx \bedm hl\ldb beb hlkh_^bgbl_ ktzfguc Zddmfmeylhf Wlbf ij_^hl\jZsZ_lky g_dhgljhebjm fuc ih\lhjguc aZimkd

y D\Zebnbpbjh\Zgguc i_jkhgZe \kh hl_lkl\bb k gZklhysbf jmdh\h^klhf ih^jZamf_\Z_l ebp dhlhju_ agZdhfu k j_]mebjh\dhc fhglZ`hf -\\h^hf wdk iemZlZpbx h[kem`b\Zgb_f we_dljhbg kljmf_glZ

y D jZ[hl_ k we_dljhbgkljmf_glhf ^hfm

ba aZ iehoh]h moh^Z aZ -we_dljhbgkljmf_gl f_glhf

y Bkihevamcl_ we_dljhbgkljmf_gl ijbgZ^e_`ghklb ijbkihkh[e_gbyb gZkZ^db \ khhl\_lkl\bb k ^Zgbgkljmdpbyfb b \ p_eyo ^ey dhlhjh hg ij_^gZagZq_g mqblu\Zy ijb avZhy mkeh\by b \b^ \uihegy_fhc jZ[hlu Bkihevah\Zgb_ we_dljhbgkljmf_gl ih gZagZq_gbx fh`_l ijb_klb d gbdgh_gbx hiZkghc kblmZpbby ljbf_g_gb_ b h[kem`b\Zgb_ dmfmeylhjgh]h bgkljmf_gl

y :ddmfmeylhj ihklZ\ey_lky g_ iheghc klvx aZjy`_ggu ey h[_ki_q_gbyb iheghc fhsghklb Zddmfmey-lhjZ aZjy`_ggu l_ _]h iheghklvx i_j_^ i_j\-uf ijbf_g_gb_f

y Bkihevamcl_ Zddmfmeylhjgmx [ZlZj_x lhevdh \ dhf[bgZpbb k bgkljmf_glhf 3 , 7 Lhevdh kfh`_l_ ij_^hl\jZlblv hiZkghkhklb ij_^f_lZfb j_]jmadm Zddmfmeylhj Z

y AZjy`Zcl_ Zddmfmeylhju lhevdh jy^guo mkljhckl\Zo j_dhf_g^m_guo ba]hlh\bl_e_^fZjy^gh_ mkljhckl\Gh ij_^mkfhlj_ggh_ ^ey hij_^_e_ggh]h \b^Z Zddmfmeylhjh\ fh`_l ijb_klb d ih`Zjghc hiZkghklb ijb bkihevah\Zgb_ _]h k ^jm]bfb Zddmfmeylhj Zfb

y ljbf_gycl_ \ we_dljhbgkljmf_glZ lhevdh ij_^mkfhlj_ggu_ ^ey Zddmfmeylhj Bkihevah\Zgb_ ^jm]bo Zddmfmeylhjh\ fh`_l ijb\_klb d ihZ fZf b ih`Zjghc hiZkghklb

y M[_^bl_kv qlh bgkljmf_gl q_g ij_`^_ q_f \klZ\eylv eylhjgmx [ZlZj_b \h \dexq fmeylhjghc [ZlZj_b \h \dexq bgkljmf_gl fh`_l ijb_klb d g_kqZkl ghfm kemqZx

y ljh_jvl_ Zddmfmeylhjgmx [ZlZj_x gZ ijhqghklv ihkZ^dZ bf__l ^\ klmi_gb nbdkZpbb

<Z`gu_ ijZ\beZ l_ogbdb [_ab iZkghklb ^ey jZ[hlu k-Zddmfmeylhjguf [ehdhf

<GBF:GBB Bkihevamcl_ lhevdh f_ggu_ Zddmfmeylhjgu_ [ZlZj_b 3 ihevah\Zgb_ Zddmfmeylhjguo [ZlZj_c ijhba_^_gguo 3 , 7 beb [ZlZj_cb [ueb ih^_j]gmlu fh^bnbdZpbyf ijb_klb d \aju\m Zddmfmeylhj ljZ\fZf b ih\j_`^_gbx bfms_kl\Z

Zddmfmeylhjguc [ehd

3 , 7 gZ bgkljmf_gl b aZjy^gh_ m

y G_ bkihevamcl_ ih\j_`^_gguc [ehd fmeylhjguc [ehd

y ?keb \j_fy jZ[hlu Zddmfmeylhj

y h [ehdZ agZqbl_evgh khdjZlb

ij_^mij_`^Zxsb_ gZ^ibkb

y G_ jhgycl_ b g_ m^Zjycl_ Zddmfmeylhjguc [ehd

y G_ bkihevamcl_ ih\j_`^_gguc [ehd fmeylhjguc [ehd

y ?keb \j_fy jZ[hlu Zddmfmeylhj

y h [ehdZ agZqbl_evgh khdjZlb

ij_djZlbl_ jZ[hlb\ghf kemqZ_ fh`_l \hag

i_j_]j_\ [ehdZ qlh ijb_^_l d h

b [Z]Z

y <kemqZ_ ihiZ^Zgby we_dljhc

]eZaZ ijhfhcl_ bo h[bevgu- dhebkl\hf qbklhc \h^u b g_f_^e_ggh

jZlbl_kv d \jZqm fh`_l ijb_klb

d ihl_j_ aj_gby

y G_ aZfudZcl_ dhglZdlu Zddmfmeylhj [ehdZ f_`^m kh[hc ijbdZkZcl_kv d dhglZdlZf dZ

[h ihdhjh\h^ysbfb ij_^f_lZfb

G_ ojZgbl_ Zddmfmeylhjguc [ehd \ f_klZo]^_ l-fi_jZ fh`_l ^hklb]Zlv beb ij_\urZ 50 °C (122 °F).

y G_ [jhkZcl_ Zddmfmeylhjguc [ehd \ f_klZo]^_ l-fi_jZ fh`_l ^hklb]Zlv beb ij_\urZ

y G_ ^himkdZcl_ ihiZ^Zgby gZ Zddmfmeylhjguc [ehd \h^u beb ^h^y AZfudhglZdlh\ Zddmfmeylhjgh]h [ehd khhhc fh`_l ijb\_klb d \hagbdg eylhjgmx [ZlZj_b \h \dexq bgkljmf_gl b- Zddmfmeylhjguc [ehd \ f_klZo ]^_ l-fi_jZ fh`_l ^hklb]Zlv beb ij_\urZ

y G_ [jhkZcl_ Zddmfmeylhjguc [ehd \ f_klZo]^_ l-fi_jZ fh`_l ^hklb]Zlv beb ij_\urZ

y G_ [jhkZcl_ Zddmfmeylhjguc [ehd fh`_l \a\Zlvky ih^ ^_ckl\b_f h]gy

y ljb ih\j_`^_gbb b g_gZ^e_`Zs bkihevah\Zgbb Zddmfmeylhj [ehdZ agZqbl_evgh khdjZlb ij_djZlbl_ jZ[hlb\ghf kemqZ_ fh`_l \hag i_j_]j_\ [ehdZ qlh ijb_^_l d h b [Z]Z

y <kemqZ_ ihiZ^Zgby we_dljhc]eZaZ ijhfhcl_ bo h[bevgu- dhebkl\hf qbklhc \h^u b g_f_^e_ggh jZlbl_kv d \jZqm fh`_l ijb_klb d ihl_j_ aj_gby

y G_ aZfudZcl_ dhglZdlu Zddmfmeylhj [ehdZ f_`^m kh[hc ijbdZkZcl_kv d dhglZdlZf dZ

[h ihdhjh\h^ysbfb ij_^f_lZfb

G_ ojZgbl_ Zddmfmeylhjguc [ehd \ f_klZo]^_ l-fi_jZ fh`_l ^hklb]Zlv beb ij_\urZ

y G_ [jhkZcl_ Zddmfmeylhjguc [ehd \ f_klZo]^_ l-fi_jZ fh`_l ^hklb]Zlv beb ij_\urZ

y <j_fy hl \j_f_gb ijhqbsZc-l_ _

lbeypbhggu_ ijhj_ab Zddmfmeylhjg fy]dhc kmohc b qbklhc dbklhqdh g_ gZijZ\eycl_ nhjkmgd-m gZ
y AZjy`Zcl_ [ehd Zddmfmeylhjh ^himkdZy _]h iheghc jZ l_evgh ij_djZlbl_ jZ[hlm k- bgkljf lhf b aZjy^bl_ [ehd _keb \u aZ kgb`_gb_ fhsghklb bgkljmf_glZ
y Gbdh]^Z g_ ih^aZjy`Zcl_ iheghk aZjy`_gguc [ehd Zddmfmeylhjh l_j_aZjy^dZ khdjZsZ_l kjhd Zddmfmeylhjz
y AZjy`Zcl_ [ehd Zddmfmeylhjh dhfgZlghc l_fi_jZlmjj_^ aZjy^ dhc]hjyq_]h [ehdZ Zddmfmeylhjh _fm hklulv
y AZjy^bl_ eblbc bhgguc Zddmfmeylhjh guc [ehd _keb \u g_ [m-^_l_ \ah\Zlvky bgkljmf_glhf ^ebl_evgh \j_fy [he__ r_klb f_kyp_\
y G_ \kdju\Zcl_ Zddmfmeylhjh wlhf \hagbdZ_l hiZkghklv dhjhadh aZfudZgby
y AZsbsZcl_ Zddmfmeylhjgmx [hl \ukhdbo l_fi_jZlmj gZijbf_j ^ebl_evgh]h gZ]j_\Zgby gZ hl h]gy \h^u b \eZ]b hiZkghklv \aju\Z
y OjZgbl_ Zddmfmeylhj \ ^bZ l_fi_jZlmj hl ^h l_ Zddmfmeylhj e_lhf \ Z\lhfh[beg hiZeb \ kbkl_fm ih^Zqb \
y <oh^ysb_ \ dhfie_dl eblbc bhgghk Zddmfmeylhju ^he`gu wdkiemyZ \Zlvky \ khhl_lkl\bb k lj-[h\Zgbb yfb aZdhgh^Zl_evkl\Z h[lh\ZjZoljb dhff_jq_kdhc lj-Zgkihg beb wdki_^blhjhf g_h[oh^bfh gZ miZdh\dm ki_pbZevgu_-ij_ gby b fZjdbjh\dm < db mkljhckl\Z d ijhdhgkmevlbjmcl_kv kh ki_pbZevgu_ ih hiZkguf fZl_jbZeZf LZd^_ ^Zcl_ f_klgu_ lj_[h\Zgby b Hgb fh]ml [ulv kljh`_ aZdj_ibl_ jZahfdgmlu_ miZdmcl_ Zddmfmeylhj lZd i_j_f_sZeky ih miZdh\d_
y <uihegycl_ lj_[h\Zgby f_klg aZdhgh^Zl_evkl\Z hlghkbl-ev ebaZpbb Zddmfmeylhjgh]h [ehdZ
MdZaZgby ih l_ogbd_ klb ^ey \ha^moh^m\hd
y <k_]^Z bkihevamcl_ aZsbJ dZkdm b j_kibjZlhj ijb bkihey \ha^moh^m\db

lbeypbhggu_ ijhj_ab Zddmfmeylhjg fy]dhc kmohc b qbklhc dbklhqdh g_ gZijZ\eycl_ nhjkmgd-m gZ
y AZjy`Zcl_ [ehd Zddmfmeylhjh ^himkdZy _]h iheghc jZ l_evgh ij_djZlbl_ jZ[hlm k- bgkljf lhf b aZjy^bl_ [ehd _keb \u aZ kgb`_gb_ fhsghklb bgkljmf_glZ
y Gbdh]^Z g_ ih^aZjy`Zcl_ iheghk aZjy`_gguc [ehd Zddmfmeylhjh l_j_aZjy^dZ khdjZsZ_l kjhd Zddmfmeylhjz
y AZjy`Zcl_ [ehd Zddmfmeylhjh dhfgZlghc l_fi_jZlmjj_^ aZjy^ dhc]hjyq_]h [ehdZ Zddmfmeylhjh _fm hklulv
y AZjy^bl_ eblbc bhgguc Zddmfmeylhjh guc [ehd _keb \u g_ [m-^_l_ \ah\Zlvky bgkljmf_glhf ^ebl_evgh \j_fy [he__ r_klb f_kyp_\
y G_ \kdju\Zcl_ Zddmfmeylhjh wlhf \hagbdZ_l hiZkghklv dhjhadh aZfudZgby
y AZsbsZcl_ Zddmfmeylhjgmx [hl \ukhdbo l_fi_jZlmj gZijbf_j ^ebl_evgh]h gZ]j_\Zgby gZ hl h]gy \h^u b \eZ]b hiZkghklv \aju\Z
y OjZgbl_ Zddmfmeylhj \ ^bZ l_fi_jZlmj hl ^h l_ Zddmfmeylhj e_lhf \ Z\lhfh[beg hiZeb \ kbkl_fm ih^Zqb \
y <oh^ysb_ \ dhfie_dl eblbc bhgghk Zddmfmeylhju ^he`gu wdkiemyZ \Zlvky \ khhl_lkl\bb k lj-[h\Zgbb yfb aZdhgh^Zl_evkl\Z h[lh\ZjZoljb dhff_jq_kdhc lj-Zgkihg beb wdki_^blhjhf g_h[oh^bfh gZ miZdh\dm ki_pbZevgu_-ij_ gby b fZjdbjh\dm < db mkljhckl\Z d ijhdhgkmevlbjmcl_kv kh ki_pbZevgu_ ih hiZkguf fZl_jbZeZf LZd^_ ^Zcl_ f_klgu_ lj_[h\Zgby b Hgb fh]ml [ulv kljh`_ aZdj_ibl_ jZahfdgmlu_ miZdmcl_ Zddmfmeylhj lZd i_j_f_sZeky ih miZdh\d_
y <uihegycl_ lj_[h\Zgby f_klg aZdhgh^Zl_evkl\Z hlghkbl-ev ebaZpbb Zddmfmeylhjgh]h [ehdZ
MdZaZgby ih l_ogbd_ klb ^ey \ha^moh^m\hd
y <k_]^Z bkihevamcl_ aZsbJ dZkdm b j_kibjZlhj ijb bkihey \ha^moh^m\db

Kjhbl_evguo hloh^h\
=bikh\hc iueb
P_f_glghc b [_lhgghc iueb
Bmkhgdh\ kmohc a_feb
G_ bkihevamcl_ \ha^moh^m\dm [jZku\Zgby beb jZkiue_gby m^h[

obfbq_kdbo kj_^kl\ ^jm]bo fZl_jbZeh\ b]hjxq_]h y G_gZ^e_`Zs__ bkihevah\Zgb_ \e_q_l aZ kh[hc Zggmebjh\Zgb_ lbb b hk\h[h`^_gb_ Ba]hlh\h \kydhc hl_lkl_gghklb q_]h \ lZdhf kemqZ_ gZ ihe\ \haeZ]Z_lky \ky hl_lkl_gghklv ke_^kl\by \hafh`guo ljZ\f-b Zevgh]h ms_j[Z dhlhju_ fh`_l hg kZf beb lj_lvb ebpZ

HibkZgb_ ijh^mdlZ b mkeml

ljhqlbl_ \k_ mdZaZgby b bgkljmdpbc- l_ogbd_ [_ahiZkghklb Mims-gby gbb mdZaZgbc b bgkljmdpbc- ihjZ_ we_dljbq_kdbf lhdhf ih`ZjZ b ljZ\f

ljbf_g_gb_ ih gZagZq_gbx

:ddmfmeylhjgZy \ha^moh^m\dZ q_gZ ^ey hqbkldb l_jjblhjbb fmkhjZ b ebkl\u

Ex[h_ ^jm]h_ bkihevah\Zgb_- fuf h[jZahf g_ h[hagZq_gh \ jmdh\h^kl_ gbx mkljhckl\Z b hiZkghklv ;eZ]h^Zjy jZ[hl_ hl g_ \u^_ey_l \j_^guo n_jm ihf_s_gbb

Bah[jZ`_ggu_ khklZ\gu_ qZklb

H[sbc \b^ bgkljmf_glZ kljZgbp_ k

M^ebgbl_evgZy ljm[dZ
<ha^moh^m\gZy ljm[Z
DghidZ hlkh_^bg_gby ljm[db
l_j_dexqZl_ev j_]mebjh\Zgby
JmqdZ
NbdkZlhj
DghidZ jZa[ehdbjh\db Zddmfmeylhjg G_ \k_ Zdk_kkmZju ijhbeexkljbjh\Zgu_ beb hibkZggu_ \oh^yl \ klZg^Zjl ie_dlZpbx

L_ogbq_kdb_ oZjZdl_jbklb

0h^_ev	PBO20H-450A
GZijy`_gb_	'&
FZdk h[t_f \ha^m oZ	fñ qZkjZat_fu aZjy^gh]h
QZklhlZ \jZs_gby	h[fbg
<_k	d]

Dhfie_dl ihklZ\db

:ddmfmeylhjgZy \ha^moh^m\dZ

Kl_jhbZgb_ ha^moh\h^ Jmdh\h^kl\h ih wdkiemZlZpbb

ljbf_qZgb_

k_ d^kl_ b pbnjh\uo h[ha-gZq_ k_mdbb fh]ml [ulv ^hims-_gu kdb^khlb[db b hi_qZldb eZa dZd_ bykljmf_gl 3, 7 ih-klhyg gkAmlky dhfiZgby hklZ\ey_l a ljZ_jh \ghkblv baf_g_gby \ md a^k_ ogbq_kdb_ oZjZdl_jbklb ie_dlZpbx [_a ij_^\Zjbl_evg-h]h m gby

JZ[hZ kbgkljmf_glhf

JJ?>MHJ?@>?GB?

. ogbd_ ijh^_^gb_f j_]mebjh\d jh\ljZ\ydb jZ[hlu bgkljmf_glZ \ ih\ljZ\yl_ qlh bgkljmf_gl \ude Z Zddmfmeylhj ba\e_q_g

K[hjdZ \ha^moh\h^Z jbk

l_j_^ k[hjdhc ljm[hd \ha^moh^m\d m[_^bl_kv qlh i_j_dexqZl_ev j_]m kdhjhklb gZoh^blky \ \ud-exq_g eh gbb

Mk+Zgh\bl_ gZ]g_lZl_evgmx-ljm[d imk-^bl_kv qlh ljm[dZ \ha^moh^m\db aZdjie_gZ

\ Zlfh.k- lj_^mij_`^_gbG_ \dexqZcl_ \ha^moh^m\dm \h \j_fy k[hjc ^_fhglZ`Z ljm[db

ljbf_qZgb_ l_j_^ jZa[hjdhc

\ha^moh^m\db m[_^bl_kv qlh i_ l_ev j_]mebjh\db kdhjhklb g \ iheh`_gbb ³2´ <ude GZ`fbl_ gZ qlh[u fh`gh [ueh hlkh_^bgblv

Jbk ljbih^gbfbl_ nbdkZlhj

g_c \ha^moh^m\ghc ljm[db qlh[u hl^_eblv gb`gxx \ha^moh^m\gm

Jbk G_ iulZcl_kv hl^_eblv ljm

eyc be b k ihfhsvx bgkljmf_glh\ mkljhckl\h b Zddmfmeylhjg j_y ki_pbZevgh jZajZ[hlZgu

b_klghc jZ[hlu ihwlhfm g_ iulZ

bkihevah\Zlv dZdb_ eb[h ^jm]b kl\Z Gbdh]^Z g_ \klZ\eycl_ b g_ l_ ihiZ^Zgby f_lZeebq_kdbo ij_^f fmeylhjghc [ZlZj_b ba aZ k[hy \ kgZ[`_gbb b \hagbdgh_gby hiZkgl l_j_^ i_j\uf bkihevah\Zgb-f Zd fmeylhjghc \ha^moh^m\db

:ddmfmeylhjgZy [ZlZj_y ihklZ\e qZklbqgh aZjy`_gghf khklhygbb

ki_q_gby iheghc fhsghklb Zddmfmeylhjgh
aZjy^bl_ _]h iheghklvx i_j_^ aZjy^dhc
ijbf_g_gb_f

AZjy^dZ Zddmfmeylhjghc [ZlZj_hZfgb

Eblb_\h bhggZy Zddmfmeylhjgh aZsbs_gZ hl]em[hdhc jZajy^db ko_fZ \udexqZ_l we_dljhbgklj Zajy`_gghf Zddmfmeylhj_ ± kljmf_gl hklZgZ\eb\Z_lky

< l_iehf ihf_s_gbb beb ihke_ gh]h bkihevah\Zgby Zddmfmeylhj fh`_l kebrdhf gZ]j_lvky g_\hafh`ghc aZjy^dm hklulv i_j_^ aZjy^dhc

MklZgh\dZ beb ba\e_q_gb_ lhj Jbkmghd

- <k_]^Z i_j_\h^bl_ i_j_dexqZl_ev ebjh\db kdhjhklb \ iheh`_gb_ i_j_^ mklZgh\dhc beb ba\e_q_gb_ dmfmeylhjgh]h [ehdZ
- Qlh[u ba\e_qv Zddmfmeylhjgmx j_x gZ`fbl_ gZ dghidm jZa[ehdZ b ba\e_dbl_ Zddmfmeylhj ba\e_dbl_ bgkljmf_glZ
- G_ ijbf_gycl_ ijb wlhf kbeu
- Qlh[u \klZ\blv Zddmfmeylhjgu mklZgh\bl_ _]h \ iZa \ hkgh\Zgbh_mgh yldb b \klZ\eycl_ ^h mihjZ ihdZ hlkh_^bg_gby Zddmfmeylhj _jg_lky \ ghjfZevgh_ iheh`_gb_

AZimkd hklZgh\dZ jbk

AZimkd

l_j__^bl_ i_j_dexqZl_ev j_]me kdhjhklb \ iheh`_gb_ ³ ´ beb HklZgh\dZ

l_j__^bl_ i_j_dexqZl_ev j_]me kdhjhklb \ iheh`_gb_ <ude

Bkihevah\Zgb_ \ha^moh^m\db

<ha^moh^m\dZ ij_^gZagZq_gZ ^ey bkihevah\Zgby \ `beuo ihf_s_gbyo Bkihevamcl_ \ha^moh^m\dm gZ \ha^mo_ ^ey m^Ze_gby fmkhjZ ih\_joghkl_c WlZ \ha^moh^m\dZ gZagZq_gZ ^ey m[hjdb ebklv_ aZjhkrbo ljZ\hc mqZkldh\ beb gby \eZ`gh]h ly`_eh]h fmkhjZ

Kh_lu ihevah\Zl_ex

<h \j_fy jZ[hlu m^_j`b\Zcl_ \ha^moZ ijb[ebabl_evgh gZ mjh\g_ a_fe_c

>\b]Zcl_kv ba klhjhgu \ klhjhgm <u ih^f_lZ_l_ ihkl_i_ggh ijh \i_j_^

K^m\Z_fuc fmkhj ebklvy ^he ^blvky gZijhlb\ <Zk

G_jbukfhevamcl_ ^ey m[hjdb lZd euo ij_^f_lh\ dZd]\ha^b [he

AZjy^dZ Zddmfmeylhjghc [ZlZj_hZfgb

AZjy^dZ Zddmfmeylhjgh aZsbs_gZ hl]em[hdhc jZajy^db ko_fZ \udexqZ_l we_dljhbgklj Zajy`_gghf Zddmfmeylhj_ ± kljmf_gl hklZgZ\eb\Z_lky

< l_iehf ihf_s_gbb beb ihke_ gh]h bkihevah\Zgby Zddmfmeylhj fh`_l kebrdhf gZ]j_lvky g_\hafh`ghc aZjy^dm hklulv i_j_^ aZjy^dhc

MklZgh\dZ beb ba\e_q_gb_ lhj Jbkmghd

- <k_]^Z i_j_\h^bl_ i_j_dexqZl_ev ebjh\db kdhjhklb \ iheh`_gb_ i_j_^ mklZgh\dhc beb ba\e_q_gb_ dmfmeylhjgh]h [ehdZ
- Qlh[u ba\e_qv Zddmfmeylhjgmx j_x gZ`fbl_ gZ dghidm jZa[ehdZ b ba\e_dbl_ Zddmfmeylhj ba\e_dbl_ bgkljmf_glZ
- G_ ijbf_gycl_ ijb wlhf kbeu
- Qlh[u \klZ\blv Zddmfmeylhjgu mklZgh\bl_ _]h \ iZa \ hkgh\Zgbh_mgh yldb b \klZ\eycl_ ^h mihjZ ihdZ hlkh_^bg_gby Zddmfmeylhj _jg_lky \ ghjfZevgh_ iheh`_gb_

AZimkd hklZgh\dZ jbk

AZimkd

l_j__^bl_ i_j_dexqZl_ev j_]me kdhjhklb \ iheh`_gb_ <ude

Bkihevah\Zgb_ \ha^moh^m\db

<ha^moh^m\dZ ij_^gZagZq_gZ ^ey bkihevah\Zgby \ `beuo ihf_s_gbyo Bkihevamcl_ \ha^moh^m\dm gZ \ha^mo_ ^ey m^Ze_gby fmkhjZ ih\_joghkl_c WlZ \ha^moh^m\dZ gZagZq_gZ ^ey m[hjdb ebklv_ aZjhkrbo ljZ\hc mqZkldh\ beb gby \eZ`gh]h ly`_eh]h fmkhjZ

Kh_lu ihevah\Zl_ex

<h \j_fy jZ[hlu m^_j`b\Zcl_ \ha^moZ ijb[ebabl_evgh gZ mjh\g_ a_fe_c

>\b]Zcl_kv ba klhjhgu \ klhjhgm <u ih^f_lZ_l_ ihkl_i_ggh ijh \i_j_^

K^m\Z_fuc fmkhj ebklvy ^he ^blvky gZijhlb\ <Zk

L_oh[kem`b\Zgb_ B K_j\bk

L_oh[kem`b\Zgb_ b hqbkldZ

<GBF:GB? l_j_^ ijh_jdhc beb ij bgkljmf_gl \udexq_g Z rl_d_j h g_gb_f jha_ldb

- DZ`^uc jZa ih hdhgqZgbb jZ[hlu g\m_fky hqbsZlv dhjimk bgklj b_gbeypbhggu_ hl_jklby h b\u_eb fy]dhc ldZgvx beb kZe Mklhcqb\u_ aZ]jyag_gby j_dhf_g mkljZgylv ijb ihfhsb fy]dhc k^hq_gghc \ fuevghc \h^_ G kkbjm bkihevah\Zlv ^ey mkljZg_ jjyag_gbc jZkl\hjbl_eb [_gabg Zl\bZ_gu_ jZkl\hju b l ijbf_g_ jZkl\hjbl_e_c fh`_l ijb_klb \j_`^_gbx dhjimkZ bgkljmf_glZ
- Bgkljmf_gl g_ lj_[m_l ^hihegbl_ k[Zadb

K_j\bk

Yl fhq l \Zr_]h we_dljhbgkljmf_g jmqZcl_ lhevdh d\Zebnbpbjh\Zggl khgZem b lhevdh k ijbf_g_gb_f hjl gu_ aZjZkguo qZkl_c Wlbf h[_kj kv [_ahiZkghklv we_dljhbgkljmf_g Kjkhd]Z\lhjbah\Zgguo k_j\bkguo p fh`gh\ijuo 3_7 jhkued_ KWWSV SLWW

Ol_Zgb b ljZgkihjlbjh\dZ

k[e_vgbo bgkljmf_gl \ aZdjulu-o ihf_ yo k _kl_kl_gghc _glbeypb_c \ r ijb l_fi_jZlmj_ \ha^moZ hl ƒK ^h h\eZ`gkklb \ha^moZ g_ [he-_ ihjlbjh\Zlv ijh^mdpbx fh`gh c \b^hf aZdjulh]h ljZgkihjlZ \ mi ijhba\h^b_ey beb [_a g__ k khoj d_Zd [m_h \b^]zky hl f_oZgbq_kdbo ih\j_ Zlfhkn_jguo hkZ^dh\ l_j_^ ljZgk jh\dhcZba\e_dbl_ Zddmfmeylhj b bgkljmf_gl ba bgkljmf_glZ


MlbebaZpby



We_dljhbgkljmf_glu Zddmfmeylhjgu_ [ZlZj_b ijbgZ^e_`jhlhjZ ^jb]Zl_ey ij_\urZ_l miZdh\dm gm`gh k^Z\Zlv gZ wdhehjb q_kdb qbklmx j_dmi_jZpbx

G_ \u[jZku\Zcl_ we_dljhbgkljmf_glZ \ Zddmfmeylhjgu_ [ZlZj_b [ZlZj_cbb \hc fmkhj

JZkrbnjh\dZ ^Zlu ba]hlh\e_gby ba^_eby



>ZlZ ba]hlh\e_gby ba^_eby aZrbmjh\ZgZ\ k_jbcghf ghf_j_ gZi_qZlZgghf gZ_dhjm k_ bgkljmf_glZ l_j\u_ pbnju h[ha_Z jZglbcghc fZkl_jkdhc

f_kyp

MKEH<BY =:J:GLBCGH=H=HLT KEM@B<:GBY

GZklhys__]ZjZglbcgh_ k\b^gZ_e\hh y\ey_lky _^bgkl_gguf ^hdm-f_g\hf l_j`^Zxsbf \Zr_ ijZ\h gZ [_kieZlgh ]ZjZglbcgh_ h[kem`b\Zgb_-;_a e_gby ^Zggh]h k\b^_l_evkl\Zjgu_ g_ ijbgbfZxlky < kemqZ_ ml_jb]ZjZglbcgh_ k\b^_l_evkl\h g_ eb\Z_lky

=ZjZglbcguc kjhd mdZaZg \ k_jlbnbdZl_ < l_q_gb_]ZjZglbcgh] dZ k_j\bkgZy kem`[Z [_kieZlgh ijhba\h^kl_ggu_ ^_n_dlu b ijhba\h^kl_ggu_ aZf_gm ^_lZe_c \ur_^rbo ba]hlh\bl_ey GZ i_jbh^ \bg_ ba]hlh\bl_ey GZ i_jbh^]ZjZglbcgh_ j_fhglZ wd\b\Ze_glguc bkijZ\guo f_gl g_ ij_^hklZ\ey_lky AZf_gm ^_lZeb i_j_oh^yl \ kh[kl_gghklvx k_j\bkZ

DhfiZgby J, L g_ g_k_l hl_lkl\Zgbkl aZ \j_^ dhlhjuc fh`_l [ulv ijbqbkj_g\kjb jZ[hl_ k we_dljhbgkljmf_glhf

<]ZjZglbcguc j_fhgl bgkljmf_gbZ\lZ gZebqbb gZ^e_`Zsbf h[jZahf ijb h[yaZl_evgh guo ^hdmf_glh\ gZklhys_]h]ZjZglbcgh] k\b^_l_evkl\Z]ZjZglbcgh]h lZehgZ ghklvx aZiheg_ggufb iheyfb lhj]h\hc hj]ZgbaZpbb b ih^ikbvx l_ey

=ZjZglbcguc j_fhgl g_ ijhba\h^kl_ggu_ ke_^mxsbo kemqZyo

ijb hlkmlkl\bb]ZjZglbcgh]h kl\Z b]ZjZglbcgh]h lZehgZ beb g_ijZ\bey

ghf bo hnhjfe_gbb

kl_lhjgv baghkZ ^bZf_ljZ dh

gdevxdhgbf bgkljmf_glh\ k [_ks_l ^\b]Zl_e_f

ijb kh\b_klghf \uoh^_ ba kljhy y

kl\Zhjgv we_dljh^\b]Zl_ey ijb h[m]c beb hieZ\e_gbb i_j\bqghc h[fhldb

nhjfZlhjZ k\Zjhqgh]h ZiiZj-ZlZ

ghjh beb imkdh aZjy^gh]h mkljhc hieZ\e_gbb \gmlj_ggbo ^_lZe_c we_dljhgguo ieZl b ^jm]bo kemqZy

keb]ZjZglbcgh k\b^_l_ev lZehg g_ ijbgZ^e_`Zl ^Zgghf-m we_ kljmf_glm beb g_ khhl_lkl-\m_l e_gghfm ihklZ\sbdhf h[jZapm

jh\bkl\q_gbb kjhdZ]ZjZglbb

ijb jhlu ldZo kZfhklhyl_evgh]h \k beb jhlhaZ

beb jhlu fhglZ we_dljhbgkljmf_glZ

pbhTu+ jZglbcghc fZkl_jkdhc

\g_k_gby dhgkljmdlb\guo baf klZadb bgkljmf_glZ \ ]ZjZglbcguc h q_f k\b^_l_evkl\mxl gZijbf_j a

kZ_e\hh\uo qZklyo dj_i_`Z dh

^_n_dlu b ijhba\h^kl_gguo beb bguo p_e

aZggu_ gakjhemq_gb_f ijb[ueb Z lZ

beb bgkljmf_glZ \ ]ZjZglbcguc

\hkkl\Zgbevghklvx iZjZf_ljh\-we_d lb ij_\urZxsbo ghjfu mklZgh\e_

ZlZKl

jh\gkjhZ\bevghc wdkiemZl-Zpbb

mklZgbgy we_dljhbgkljmf_glZ-g_ ih

mdZaZgghfm \ bgkljm-dpbb

ZlZjhby mklZgh\db gZ we_dljhbgkl

gZkZ^hd ^hihegbl_evguo ijbkihkl

kZ k_l_\h]h rgmjZ b ijb ih\j_`^_ ihiZ^Zgbb bghjh^guo ij_^f_l-h\ \ \

jZglbcgh] k\b^_l_evkl\Z]ZjZglbcgh]h lZehgZ beb g_ijZ\bey

ke_^mxsbo kemqZyo

ijb hlkmlkl\bb]ZjZglbcgh]h kl\Z b]ZjZglbcgh]h lZehgZ beb g_ijZ\bey

k g_kh[ex^_gb_f ij_^mkfh-lj_ kljmdpb_c mkeh\bc wdkiemZlZpbb ih l_ogbd_ [_ah-iZkghlkbb kljmdpbb
ijb ih\j_`^_gbb ba^_eby \ke_^ kh[ex^_gby ijZ\be ojZg_gby- b lbjh\db
ijb kbevghf \gmlj_gg_f aZ]-jyaf kljmf_glZ
ijb jZ[hl_ k i_j_]jmadhc -[_gja^hmgkhjgmhc qZklb >ey \uykg_gby f_glZ baf_g_gbb p_lZ qZrdbg_bkfmZh\guhklb ihdmiZl_ex k-e_^mkp_ie_gby \ j_amevlZl_ i_j_]j_\ bkijZ\ghklb hklZevguo ^_lZe_c mkljhckl\Z
ijb h[ju_ rgmjZ klZjl_jZ ijb mkljZgyxlky aZ kq_l ihdmiZl_ey jbh^bq_kdhf l_ogbq_kdhf h[kemk`b\Z-gb_ h[kem`b\Z-gb_ beb hieZ\e_gb_ hihjguo ih^ rZlmgZ b ihjrg_\h]h iZevpZ
gZ \k_ \b^u jZ[hl \uihegy_fu_ jbh^bq_kdhf l_ogbq_kdhf h[kemk`b\Z-gb_ j_]mebjh\db qbkld_ aZf_g_hkZ\ey_l fZl_jbZeh\ b ^j
gZ g_bkijZ\ghklb \hagbd-rb_^hqjbampZvg]h\u_ aZ`bfu rbgu wdkiemZlZpbb mklZgh\e_ggufjhiZkihh^jhh\u rebnh\Zevguo b e_glh ba^_eby GZijbf_j i_j_]j_\ fZa^bgebmybevlju]heh\db r_klb]jg_kh[ex^_gb_ lj_[h\Zgbc d-khkkZ\mgb_dgZZkZ^db b li q_kl\m lhieb\ghc kf_kb ih\e_drbq[u\kuljhb ba kljhy ihjrg_\hc]jmiiu [_amfkejh\gmufhevgu_ s_ldb ijb\h^gu_ ijbagZdhf wlh]h y\ey_lky aZe_]kgZbe_vgbjdb aZsblgu_ dh`meb g_\h]h dhevpZ b beb gZebqbs-bpZjjZebgbb gZijZ\eyxsb_ j_a ihl_jlhkl_c gZ \gmlj_gg_c ih\m-ijehglhk-gby ih^rbigbddb am[qZlu pbebg^jZ b ih_joghklb ihjrg-y gb_ beb hieZ\e_gb_ hihjguo ih^ rZlmgZ b ihjrg_\h]h iZevpZ
gZ \g_rgb_ b \gmlj_ggb_ aZ]-jyaf pZjZibgu lj_sbgu ih\j_`^_g-by rb_ \ ijhp_kk_ wdkiemZlZpbb ihjlbjh\db
ijb jZ[hl_ we_dljhbgkljmf_glhf^kei_jg]jmadhc b aZdebgb\Zgb_f hkgZekZ\dgZyh^dhef`_g [ulv \uiheg_g ihk k\b^_l_evkl\mxl aZ^bju baf_g_jbe-Zkgby_liZhlj_[bl_ey ?keb ihlj_[bl hl l_fi_jZlmju mihjguo b ijbkhjeZ\og gZ aZf_gm lh \ ex[hf rZc[ aZ`bfgh]h iZljhgZ \uoh^Zwbla]khjby gkljmf_glZ [m^_l hldZaZj_^mdlhjZ
ljhnbeZdlbq_kdh_ h[kem`b\Z-gb_ bwcghdljZehg_ beb d\blZgpbb k_bgkljmf_glZ qbkldZ ijhfu\dZ_gkfZabdZh^ibkZg \eZ^_evp_f aZf_gZ iuevgbdh\ ihjrg_\uo b miehl gbl_evguo dhe_p \ ]ZjZglbcguc i_jbh^ y\ey_lky ieZlghc mkem]hc
Kjhd kem`[u ba^_eby khklZ\ey_l]h^Z
Kjhd ojZg_gby ±]h^Z G_ j_dhf_g^m_lky d wdkiemZlZpbb ih bkl_q_gbb e_l ojZg_ gby k ^Zlu ba]hlh\e_gby dhlhjZy mdZaZgZ \ k_jbcghf ghf_j_ gZ wlbd_ld_ bgkljmf_glZ [_a ij_^\Zjbl_evghc ijh_jdb- hij_^_e_ gb_ ^Zlu \uimkdZ kfhljbl_ jZg__ \ Jmdh \h^kl_ ihevah\Zl_ey
H \hafh`guo gZjmr_gbyo baeh`_gguo

P.I.T. WARRANTY CERTIFICATE

Place of seal

Product Name_____

Product Serial Number ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘

Charger Serial Number ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘ ‘

Sale Date _____

Trade Organization Name _____

Dear customer!

7KDQN \RX IRU SXUFKDVLQJ WKH 3 , 7 WRRO DQG ZH KRSH V

In the process of manufacturing the P.I.T. tools pass multilevel quality control, if nevertheless your product will need maintenance, please contact the authorized P.I.T. service centers.

Attention!

:KHQ EX\LQJ DVN D VHOOHU WR FKHFN WKH FRPSOHWHQHVV
:DUUDQW\ &HUWL¿FDWH WKH :DUUDQW\ &DUG WKH ER[HV VH
VHDO RI WKH WUDGH RUJDQL]DWLRQ LQ WKH SUHVHQFH RI WKH &

Warranty

%\ WKLV :DUUDQW\ &HUWL¿FDWH 3 , 7 FRPSDQ\ JXDUDQWHHV
nature.

In the event any of the above defects are detected during the warranty period, the specialized P.I.T. service centers shall repair the product and replace the defective spare parts free of charge.

The warranty period for P.I.T. electric machines is 12 months from the date of sale.

“The warranty maintenance terms acknowledged and accepted. The operability and completeness of the product are checked in my presence. No claims on quality and appearance.”

Buyer’s Signature_____ Surname (legibly) _____

Phone _____

=:J:GLBCGH? K<B>?L?EVKL<H G: BGKLJMF

GZbf_gh\Zgb_ ba^_ebyBBBBBBBBBBB
K_jbcguc ghf_j ba^_eby‘‘‘‘‘‘‘

K_jbcguc ghf_j aZjy^gh]h m‘k‘l‘j‘h‘c‘k‘l‘f‘Z‘‘‘‘

M.П.

>ZlZ ijh^Z`b ©BBBBBª BBBBBBBBBBBBBBBBBBB
GZbf_gh\Zgb_ lhj]h\hc hj]ZgbaZpbb
M\Z`Z_fuc ihdmiZl_ev

;eZ]h^Zjbf <Zk aZ ihdmidm bgkljmf_glZ J , L b gZ^__fky qlh <
k\hbf \u[hjhf
ljb g_h[oh^bfhklb h[kem`b\Zgby <Zr_]h ba^_eby h[jZsZcl_kv-\ Z\l
\bkgu_ p_glju J , L <k_ k_j\bkgu_ p_glju ij_^klZ\e_gu gZ kZcl_ Z

<gbfZgb_
ljb ihdmid_ lj_[mcl_ m ijh^Z\pZ ijh_jdb jZ[hlhkihkh[ghklb bgk
ie_dlghklb Z lZd`_ aZiheg_gby]ZjZglbcgh]h k\b^_l_evkl\Z]ZjZg
©AZihegyxlky ijh^Z\phfª b ijhklZgh\db i_qZlb lhj]h\hc hj]Zgba
k\b^_l_evkl_ b]ZjZglbcguo lZehgZo

=ZjZglby
GZ hkgh\Zgbb ^Zggh]h]ZjZglbcgh]h k\b^_l_evkl\Z dhfiZgby J , L
^_n_dlh\ ijhba\h^kl_ggh]h oZjZdl_jZ
?keb \ l_q_gb_]ZjZglbcgh]h kjhdZ \ <Zr_f ba^_ebb h[gZjm`Zlky n
ki_pbZebabjh\Zggu_ k_j\bkgu_ p_glju J , L [_kieZlgh hlj_fhglbjn
gyl ^_n_dlgu_ aZiZkgu_ qZklb
=ZjZglbcguc kjhd gZ we_dljhbgkljmf_glu J , L khklZ\ey_l f_kyp

©K mkeh\byfb]ZjZglbcgh]h h[kem`b\Zgby hagZdhfe_g Z JZ[hlhk
ghklv ba^_eby ijh_j_gu \ fh_f ijbkmlkl\bb lj_l_gabc d dZq_kl\m
bf_xª

I h ^ i b k v i h d m i Z l _ e y B B B B B B B B B B B B B B B B B B B
\h BBBBBBBBBBBBBBBBBBBBBBBBB
L_e_nhgBBBBBBBBBBBBBBB

P.I.T. WARRANTY CARD

Name_____
Serial Number_____
Sale Date _____20__
Date of Receipt from Repair ____20__

P.I.T.

Name_____
Serial Number_____
Sale Date _____20__ Place of Seal
(Filled out by a Seller)
WARRANTY REPAIR CARD
Date of Acceptance for Repair _____20___
Application for Repair _____
Customer _____
Phone (Address)_____
Cause of Application_____
Date of Receipt from Repair _____20__
The Tool is checked in my presence_____
(The Order shall be performed in a Service Center) (Signature)

Name_____
Serial Number_____
Sale Date _____20__
Date of Receipt from Repair ____20__

P.I.T.


Name_____
Serial Number_____
Sale Date _____20__ Place of Seal
(Filled out by a Seller)
WARRANTY REPAIR CARD
Date of Acceptance for Repair _____20___
Application for Repair _____
Customer _____
Phone (Address)_____
Cause of Application_____
Date of Receipt from Repair _____20__
The Tool is checked in my presence_____
(The Order shall be performed in a Service Center) (Signature)

Name_____
Serial Number_____
Sale Date _____20__
Date of Receipt from Repair ____20__

P.I.T.

Name_____
Serial Number_____
Sale Date _____20__ Place of Seal
(Filled out by a Seller)
WARRANTY REPAIR CARD
Date of Acceptance for Repair _____20___
Application for Repair _____
Customer _____
Phone (Address)_____
Cause of Application_____
Date of Receipt from Repair _____20__
The Tool is checked in my presence_____
(The Order shall be performed in a Service Center) (Signature)

=:J:GLBCGUC L:EHG J L



P.I.T.

Media account

pit_global PIT Global YouTube PIT Global

bod@pit-tools.com www.pit-tools.com

Сделано в КНР / Made in China